

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 20 Dec 2021

Preliminary Advice

Vehicle No	: GBD6848L	Accident Date	: 11/12/2021
Make	: FIAT DOBLO CARGO MAXI	Policy No.	: DMCVSNW00028492100
Assignment Date	: 20/12/2021	Excess	: S\$2,000.00
Date of Inspection	: 20/12/2021	Est. Duration of Repair	: 7
Inspection At	: DING AUTO PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,206.55
Revised Amount	:S\$	6,821.55
Check Items (Estimated)	:S\$	7,910.00
Total	:S\$	14,731.55
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	22,000.00
COE / PARF Rebate	:S\$	6,496.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,504.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on Lump Sum

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.