

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 4 March 2022 11:08 AM
To: 'Kenneth Ding'; 'SA 0406'; 'Accounts (Ding Auto)'
Cc: SUR
Subject: RE: GBD 6848L-DOA: 11/2/2021 (CHINA TAIPING OD)
Attachments: GBD 6848L SUPPLEMENTARY.pdf

Dear Henry,

Above has been approved.

Lump Sum Repair Not Exceeding \$13,000/- or whichever, (Excess \$2000/-).

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kenneth Ding [mailto:kenneth.ding@dingauto.sg]
Sent: Tuesday, 28 December 2021 3:55 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; 'SA 0406' <sa0406@dingauto.sg>; 'Accounts (Ding Auto)' <accounts@dingauto.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD 6848L-DOA: 11/2/2021 (CHINA TAIPING OD)

Dear Veron,

Good day to you.

Well noted.

Dear Henry,

Please follow up.

Thank you

Best Regards,
Kenneth Ding

HP: 92313123

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, December 28, 2021 3:25 PM
To: ding@dingauto.sg; kenneth.ding@dingauto.sg
Cc: SUR
Subject: GBD 6848L-DOA: 11/2/2021 (CHINA TAIPING OD)

Dear Sir,

As instructed by our client , please proceed to repair the **insured vehicle GBD 6848L at Lump Sum Repair Not Exceeding \$13,000/- or whichever, (Excess \$2000/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)