



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(SMU6931J)
Policy No:		Date of Loss:	17/12/2021
Vehicle Reg. No.:	GBC5517D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	PHUA MING HONG	Driver (Insured):	LEE WEI NENG

Make/Model:	MERCEDES-BENZ 316CDI/3665, 2.1 (A)	Vehicle Reg. Date:	22/01/2013
Vehicle Colour:	YELLOW		
Engine No:	65195531279705	Chassis No:	WDB9066332S718047
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

*Not Authorized
L1Rm 84200d
Repairing After Repair
6 days*

Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	3,504.00
Labour	10.00
Paintwork Labour	3,030.00
Towing	0.00
	0.00
Gross Total (\$\$)	
	6,544.00
+ GST 7.00% (\$\$)	
	458.08
Nett Amount (\$\$)	
	7,002.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

ASS. REC. BY:

REF:

Aspire 3

From

Est

AIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Dec 2021)

Parts: N/A MERCEDES-BENZ 316CDI/3665 2.1 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC5517D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

GBC5517D
TP/CHINA

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	<i>Re</i> *395.00 F ✓
2	1		*1 PC REAR BUMPER RH REFLECTOR	0.00	0.00	<i>Re</i> *12.00 F ✓
3	1		*1 PC REAR BUMPER RH SIDE PAD	0.00	0.00	<i>Re</i> *110.00 F ✓
4	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	<i>Re</i> *460.00 F X
5	1		*2 PCS REAR BUMPER TOP CLIPS @3/PC	0.00	0.00	<i>Re</i> *6.00 F ✓
6	1		*1 PC REAR BUMPER RH TOP PROTECTOR	0.00	0.00	<i>Re</i> *20.00 F ✓
7	1		*1 PC RH TAILLAMP COVER	0.00	0.00	<i>Re</i> *185.00 F X
8	1		*1 PC RH TAILLAMP HOUSING	0.00	0.00	<i>Re</i> *230.00 F ✓
9	1		*1 PC RH TAILLAMP SOCKET	0.00	0.00	<i>Re</i> *39.00 F ✓
10	1		*3 PCS RH TAILLAMP CLIPS @3/PC	0.00	0.00	<i>Re</i> *9.00 F ✓
11	1		*1 PC RH TAILGATE	0.00	0.00	<i>Re</i> *1,450.00 F ✓
12	1		*1 PC RH TAILGATE LOWER HINGE	0.00	0.00	<i>Re</i> *165.00 F X
13	1		*1 PC RH TAILGATE INNER RUBBER	0.00	0.00	<i>Re</i> *230.00 F ✓
14	1		*1 PC RH TAILGATE EMBLEM (316 CDI)	0.00	0.00	<i>Re</i> *105.00 F ✓
15	1		*1 PC LH TAILGATE EMBLEM (SPRINTER)	0.00	0.00	<i>Re</i> *88.00 F ✓
Total Parts (\$\$)						3,504.00

F=Franchise part.

R1 Tailgate lock Re 220.00 ✓

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC STICKER - 70KM.H	<i>Re</i> 10.00 ✓
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, BUMPER SIDE PAD, RH TAILGATE, LOCK ASSY, TO CUT, WELD & RENEW RH TAILLAMP PANEL, KNOCK & REPAIR REAR RH SIDE PANEL, LH SIDE PANEL, REAR END PANEL, REAR RH CORNAL FLOOR BOARD AND REALIGN THE SAME	New	1,000.00 <i>800</i>
2	PUTTY & RESPRAY ON RH & LH TAILGATE, BOTH SIDE PANELS, TAILLAMP PANEL AND REAR RH CORNAL FLOOR BOARD PANEL & ALL AFFECTED AREAS	New	1,200.00 <i>1000</i>
3	TO REWRITE ADVERTISEMENT	New	800.00 <i>550</i>
4	RUSTPROOFING	New	30.00 ✓
Gross Labour Cost (\$\$)			3,030.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS