TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

SJB 4761 G

Your ref:

SHA 9516 U

20 December 2021

AXA INSURANCE PTE LTD

BY EMAIL motor.survey@axa.com.sg ONLY

8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811

Attn: Motor Claims Department

Dear Sir/Madam,

DATE OF ACCIDENT: 18 Dec 2021

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by **GUI AH BAH** to notify you of a road traffic accident on **18 Dec 2021** at about **10:50 HRS** along **PIE TWDS TUAS B4 PAYA LEBAR EXIT** our client's vehicle **SJB 4761 G & SHA 9516 U** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



Twincar Automotive Pte Ltd