



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :

Quotation No. : QO21/12-1147	Quotation Date : 20/12/2021	Terms : 60 DAYS
Vehicle No. : SMK5332Y	Chassis No. : KMHK281GUKU024579	Policy Number :
Model : HYUNDAI KONA		Date of Accident : 18/12/2021
Third Party Insurer : ECICS		TP Vehicle No. : SMX931H
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER / BR	1	495.6500	495.65 ✓
2	REAR BUMPER CLIPS @ 10PCS / nec	10	4.5000	30 ✓ 45.00
3	REAR BUMPER SIDE RETAINER @ 2PCS / BR	2	85.2500	170.50 ✓
4	REAR BUMPER TOW COVER / BR	1	25.2000	25.20 ✓
5	REAR BUMPER UPPER CENTER GARNISH (FOLLOW VEHICLE COLOUR) / BR	1	296.3500	296.35 ✓
6	REAR BUMPER LOWER CENTER GARNISH (SILVER COLOUR) / BR	1	126.9500	126.95 ✓
7	REAR BUMPER REVERSE SENSOR @ 4PCS / shorted	4 2	189.4000	378.80 ✓ 757.60
8	REAR BUMPER UNDER LOWER CENTRE COVER (BLACK COLOUR) / BR	1	295.8000	295.80 ✓
9	REAR BUMPER SIGNAL LAMP @ 2pcs (RH) / CVT	2 1	257.1000 ✓	514.20
10	REAR ANTENNA SMART KEYLESS / shorted	1	128.2000	128.20 ✓
11	REAR REINFORCEMENT / DD	1	335.8000	335.80 ✓
12	REAR REINFORCEMENT ARM @ 2PCS / BT	2 1	158.0000 ✓	316.00
13	REAR REINFORCEMENT UPPER BRACKET @ 2PCS / CRU	2	38.0000	76.00 ✓
14	REAR REINFORCEMENT LOWER BRACKET @ 3PCS / CRU	3	28.0000	84.00 ✓
15	REAR BLIND SPOT SENSOR ? ✓ Shorted	1	980.5700	980.57 ✓
16	REAR END PANEL / DD	1	785.6500	785.65 ✓
17	REAR END PANEL TOP GARNISH ? X NN	1	235.2000	235.20
18	REAR SPARE TYRE PANEL / DD X Repair	1	885.9000	885.90
19	REAR SPARE TYRE PANEL FLOOR BOARD X NN	1	278.5000	278.50
20	REAR TAILGATE / DD	1	1,928.9500	1540 ✓ 1,928.95
21	REAR TAILGATE HINGE @ 2pcs X NN	2	155.6000	311.20
22	REAR TAILGATE ABSORBER @ 2pcs X NN	2	198.5000	397.00

C/F

0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :

Quotation No. : QO21/12-1147	Quotation Date : 20/12/2021	Terms : 60 DAYS
Vehicle No. : SMK5332Y	Chassis No. : KMHK281GUKU024579	Policy Number :
Model : HYUNDAI KONA		Date of Accident : 18/12/2021
Third Party Insurer : ECICS		TP Vehicle No. : SMX931H
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	REAR TAILGATE OUTER MOULDING + NN	1	245.2000	245.20
24	REAR TAILGATE "HYUNDAI" EMBLEM - nec	1	55.0000	55.00 ✓
25	REAR TAILGATE "KONA" BADGE - nec	1	45.0000	45.00 ✓
26	REAR TAILGATE "ELECTRIC" BADGE - nec	1	45.0000	45.00 ✓
27	REAR TAILGATE REFLECTOR @ 2pcs + NN	2	403.5000	807.00
28	REAR TAILGATE TRIM BOARD + NN	1	228.8000	228.80
29	REAR TAILGATE TRIM BOARD CLIPS @ 10PCS x NN	10	5.0000	50.00
30	REAR TAILGATE LOCK ? x NN	1	213.7000	213.70
31	REAR TAILGATE NO PLATE LAMP @ 2PCS x NN	2	85.0000	170.00
32	REAR TAILGATE STRIKER (CATCH) x NN	1	89.0000	89.00
33	REAR WINDSCREEN MOULDING - nec	1	198.0000	198.00 ✓
34	REAR WEATHERSTRIP - TN	1	200.0000	200.00 ✓
35	REAR FENDER @ 2PCS - REPAIR x Repair	2		
36	LESS 20%	1	-2,363.3800	-2,363.38
37	REAR NO PLATE & CASING - CVT	1	60.0000	60.00 40
38	REAR WINDSCREEN GLASS SEALANT - nec	1	60.0000	60.00 40
39	TOWING FEE - nec	1	100.0000	100.00 60
40	TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR	1	100.0000	100.00 30
41	TO REMOVE & TRANSFER REAR WINDSCREEN GLASS TO THE NEW TAILGATE.	1	200.0000	200.00 50
42	TO REMOVE AND REFIT REAR INTERIOR FITTINGS, TRIMMINGS, GARNISH FLOOR CARPET TO ENABLE REPAIR.	1	50 120.0000	120.00 30

6707.57
-20%
5366.05

C/F 0.00

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : VIVIAN TAN EE WI Tel : Email :	Customer : GRAB RENTALS PTE LTD 3 MEDIA CLOSE #07-03 SINGAPORE 138498 Attn : Tel : Fax No. :
--	--

Quotation No. : QO21/12-1147	Quotation Date : 20/12/2021	Terms : 60 DAYS
Vehicle No. : SMK5332Y	Chassis No. : KMHK281GUKU024579	Policy Number :
Model : HYUNDAI KONA	Date of Accident : 18/12/2021	
Third Party Insurer : ECICS	TP Vehicle No. : SMX931H	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
43	TO REMOVE & REARRANGE ELECTRICAL WIRING SYSTEM FOR FACILITATE REPAIR.	1	100.0000	30 100.00
44	TO DISCONNECT & CONNECT BACK ELECTRICAL POWER.	1	200.0000	80 200.00
45	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	1	120.0000	30 120.00
46	TO REMOVE, REPLACED DAMAGED BODYPARTS, REPAIR & REALIGN BODYWORK & WHERE CONSISTANT TO THE ACCIDENTS.	1	1400 2,000.0000	1300 2,000.00
47	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	2810 2690 1,600.0000	1000 1,600.00

total- ~~8050.05~~ 8176.05

Steve (LKK)

21/12/21, 1.00pm

without Prejudice

L/S

L/S - ~~6444.84~~ 6540.84
= ~~6450~~ 6550

Resurvey After Spray

10 days

Sub Total	14,113.54
GST(7.00%)	987.95
Total (SGD)	15,101.49

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800