



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 18.12.2021
Emailed : 09.02.2022, 11.25am
Date Survey : 20.12.2021

VEHICLE NO : SKX 169 R
MODEL : KIA STINGER 2.0
WIP : 44208

Material	:	\$	16,170.80
Labour	:	\$	4,120.00
Sub-Total	:	\$	20,290.80
	:	\$	-
Less Excess	:	\$	1,600.00
Total	:	\$	18,690.80
GST 7%	:	\$	1,308.36
Grand Total	:	\$	19,999.16
Finalise By/Date	:	LOI / 09/02/2022	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 21/12/2021	Cust No/Name	LCV12069/KIRAN PAL SINGH
	Reg No/Reg Date	SKX169R / 19/02/2020
	Date In/Mileage	21/12/2021/ 52001
	Chassis/Package	KNAE351AML6080066
	Engine No	G4CLKH027498
	Make/Model	KIA/STINGER 2.0 A GAA3 RED LEATHER
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	09/02/2022/ 11:16	BLC	260 / AiTing	44208		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							20.00
SUNDRIES							600.00
E PNT88000							100.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, FRONT H/LAMP SUPPORT							
PANEL, REPAIR RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST							
AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							
E PNT88000							1050.00
REMOVE & INSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR							
E PNT98000							30.00
RESPRAY ON FRONT BUMPER, BONNET, RH FRONT FENDER FENDER							
A 90000001							120.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE							
B WHEELALIGNMENT							30.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							400.00
REPLACE RH FRONT TIRE, REPLACE TIRE VALVE, CONDUCT WHEEL							
BALANCING							400.00
A 90000001							240.00
REPLACE FRONT DASHBOARD AND AIR BAG SYSTEM							
A 90000001							80.00
REPLACE FRONT & BACK SEAT BELTS & IMPACT SENSORS							
E PNT88000							50.00
REPLACE FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST							
M SUNDRY							80.00
APPLY SEALANT ON FRONT WINDSCREEN GLASS							
S SPECIALISTJOB							50.00
SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME							
S SPECIALISTJOB							80.00
VACUUM & TOP UP A/COND GAS							
S TYRESALES2							580.00
SUPPLY RH FRONT TIRE							



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12069/KIRAN PAL SINGH Reg No/Reg Date SKX169R / 19/02/2020 Date In/Mileage 21/12/2021/ 52001 Chassis/Package KNAE351AML6080066 Engine No G4CLKH027498 Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK
21/12/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/02/2022/ 11:16	BLC	260 / AiTing	44208			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X EXC								-1600.00
EXCESS								
S SPECIALISTJOB							240	✓ 220.00
SUPPLY & REPLACE FRONT WINDSCREEN GLASS SOLAR FILM - RIKECOOL								
M SUNDRY								? 204.80
SUPPLY WIRING ASSY-FEM (AFTER 20% DISCOUNT) → Quoted under Parts								
X COVER-FR BUMPER					1.00	✓ 646.00	20.00	516.80
X LOGO ASSY-KIA SUB					1.00	✓ 45.00	20.00	36.00
X GRILLE-FRONT BUMPER					1.00	✓ 391.00	20.00	312.80
X GRILLE ASSY-RADIATOR					1.00	✓ 444.00	20.00	355.20
X ABSORBER-FRONT BUMPER ENERGY					1.00	✓ 105.00	20.00	84.00
X COVER ASSY-AIR CURTAIN,RH					1.00	✓ 126.00	20.00	100.80
X LIP ASSY-FRONT BUMPER					1.00	✓ 22.00	20.00	17.60
X MOULDING-FRT BPR LICENSE PLATE					1.00	✓ 35.00	20.00	28.00
X CAP-FRONT HOOK					1.00	✓ 9.00	20.00	7.20
X STIFFNER-FR BPR LWR					1.00	✓ 127.00	20.00	101.60
X BRKT ASSY-FRT BUMPER SIDE MTG,					1.00	✓ 15.00	20.00	12.00
X BEAM COMPLETE-FR BUMPER					1.00	✓ 620.00	20.00	496.00
X CARRIER ASSY-FRONT END MODULE					1.00	✓ 697.00	20.00	557.60
X GLASS ASSY-WINDSHIELD					1.00	✓ 2009.00	20.00	1607.20
X MOULDING-WINDSHIELD GLASS					1.00	✓ 92.00	20.00	73.60
X MOULDING ASSY-W/SHLD SIDE,RH					1.00	✓ 94.00	20.00	75.20
X MOULDING ASSY-W/SHLD SIDE,LH					1.00	✓ 94.00	20.00	75.20
X BRACKET-W/S MLDG MTG,RH					1.00	✓ 27.00	20.00	21.60
X BRACKET-W/S MLDG MTG,LH					1.00	✓ 27.00	20.00	21.60
X LAMP ASSY-HEAD,RH					1.00	✓ 3977.00	20.00	3181.60
X SENSOR ASSY-A TYPE CRASH					2.00	✓ 96.00	20.00	153.60
X MODULE ASSY-AIR BAG CONTROL					1.00	✓ 810.00	20.00	648.00
X MODULE ASSY-KNEE AIR BAG					1.00	✓ 595.00	20.00	476.00
X AIR BAG ASSY-PASSENGER					1.00	✓ 1163.00	20.00	930.40
X MODULE ASSY-STRG WHEEL AIR BAG					1.00	✓ 1516.00	20.00	1212.80
X SENSOR-ANGULAR VELOCITY					1.00	✓ 375.00	20.00	300.00
X CONTACT ASSY-CLOCK SPRING					1.00	✓ 169.00	20.00	135.20

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 21/12/2021	<table> <tr><td>Cust No/Name</td><td>LCV12069/KIRAN PAL SINGH</td></tr> <tr><td>Reg No/Reg Date</td><td>SKX169R / 19/02/2020</td></tr> <tr><td>Date In/Mileage</td><td>21/12/2021/ 52001</td></tr> <tr><td>Chassis/Package</td><td>KNAE351AML6080066</td></tr> <tr><td>Engine No</td><td>G4CLKH027498</td></tr> <tr><td>Make/Model</td><td>KIA/STINGER 2.0 A GAA3 RED LEATHER</td></tr> <tr><td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV12069/KIRAN PAL SINGH	Reg No/Reg Date	SKX169R / 19/02/2020	Date In/Mileage	21/12/2021/ 52001	Chassis/Package	KNAE351AML6080066	Engine No	G4CLKH027498	Make/Model	KIA/STINGER 2.0 A GAA3 RED LEATHER	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	LCV12069/KIRAN PAL SINGH														
Reg No/Reg Date	SKX169R / 19/02/2020														
Date In/Mileage	21/12/2021/ 52001														
Chassis/Package	KNAE351AML6080066														
Engine No	G4CLKH027498														
Make/Model	KIA/STINGER 2.0 A GAA3 RED LEATHER														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/02/2022/ 11:16	BLC	260 / AiTing	44208			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	CRASH PAD ASSY-MAIN				1.00	✓ 2146.00	20.00	1716.80
X	GUARD-AIR				1.00	✓ 88.00	20.00	70.40
X	S/BELT ASSY-FR RH				1.00	✓ 420.00	20.00	336.00
X	S/BELT ASSY-FR LH				1.00	✓ 420.00	20.00	336.00
X	SEAT BELT PRETENSIONER,RH				1.00	✓ 194.00	20.00	155.20
X	SEAT BELT PRETENSIONER,LH				1.00	✓ 194.00	20.00	155.20
X	S/BELT ASSY-RR,RH				1.00	✓ 398.00	20.00	318.40
X	S/BELT ASSY-RR,LH				1.00	✓ 398.00	20.00	318.40
X	BRACKET, IU ADHESIVE				1.00	✓ 26.00	00.00	26.00
X	PANEL-UNDER COVER FRONT	→ Supp.			1.00	283.00	20.00	226.40
X	COOLANT (4L)	→ Supp.			1.00	26.00	20.00	20.80
X	SENSOR & UNIT ASSY-ACTIVE HOOD				1.00	✓ 936.00	20.00	748.80
Z	TEXT							
AIG OD CLAIM								
DOA : 18.12.21								
SURVEYOR STEVE LKK 20.12.21								
POLICY NO : 2070016788 REPAIR 10 DAYS								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	15,966.00	Nett	18,690.80
Labour	3,060.00	7% GST on	1308.36
Standard Menu	0.00		
Specialist Job	930.00	Total Payable	19,999.16
Diagnostics Job	0.00		
Sundry/Others	-1,265.20		
Total(w/o GST)	18,690.80		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SKX 169 R

<u>Materials</u>		<u>Cost (\$)</u>
1	Panel-Under cover front	283.00 ✓ BR
2	coolant (4L)	26.00 ✓ nec
Total		309.00
Less 20% discount		61.80
Total after discount		247.20
7% GST		17.30
Grand total		<u>264.50</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SKX169RWIP: 44208 (ADDITIONAL PARTS CHANGE)

SINO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Pane F-Under Cover Front de	? / SUPP			
2	Sensor & Unit Assy-Active HANDLED	? / SUPP			
3	ABSORBER -FR BUMPER ENERGY	? / SUPP			
4	COVER ASSY-AIR CURTAIN/RRA CR	? / SUPP			
5	STIFFENER-FR BOR LWR CR	? / SUPP			
6	BEAM COMPLETE-FR BUMPER bt	? / SUPP	23/12/21		
7	CARRIER ASSY-FR END MODULE CR	? / SUPP			
8	GUARD-AIR CR	? / SUPP		23.12.2021	
9	COOLANT ne	? / SUPP			
10	Webbing guide RR Seat Back	? / SUPP			89473J5000LK
11	Webbing 1H	? / SUPP			89373J5000LK
12	BRACKET FOR RR MOUNTING RR	? / SUPP			91370J5000LK
13	PACK ASSY-FR BOR SCS MGR RM	? / SUPP			86514J5000
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
23/12/2021	Ln

MODEL: stingerSURVEYOR: stave UK

Work Order: R001619
 License: SKX 169 R
 Technician: CHOO
 Mileage: 50427
 Date: 25.1.22 19:12

Kia : Stinger : Rear Wheel Drive (Standard Suspension) : with 19" Wheel : 2017- (CK)

Front : Left

Actual	Before	Specified Range
-0°44'	-0°43'	-1°00' 0°00'
7°11'	7°11'	6°30' 7°30'
0°06'	0°22'*	0°00' 0°12'
14°21'	14°20'	
13°37'	13°37'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°13'*	-1°20'*	-1°00' 0°00'
8°02'*	8°02'*	6°30' 7°30'
0°05'	0°24'*	0°00' 0°12'
14°15'	14°22'	
13°02'	13°02'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°29'	0°37'	
-0°51'	-0°51'	
0°06'	-0°02'	
0°11'	0°46'*	0°00' 0°24'

Rear : Left

Actual	Before	Specified Range
-1°44'*	-1°38'	-1°42' -0°42'
0°22'*	0°20'*	0°06' 0°18'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°04'*	-2°11'*	-1°42' -0°42'
0°18'*	0°20'*	0°06' 0°18'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°20'	0°33'	
0°40'*	0°39'*	0°12' 0°36'
0°02'	0°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



Stinger(CK)/2020/G 2.0 T-G..



VCI



Fault Code Searching

Rescan

Clear DTC

Read DTC

Save



22/22

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESHIFTER	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver.

M-E-K-01-00-0263

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0202

OS Ver.

Android 10