

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

MOTOR CLAIMS DEPT

ATTENTION:

CONTACT: 62222366

FAX NO: 62221033

EST/QUOTE NO. SQ007049

DATE 23/12/2021

ACCIDENT DATE: 14/12/2021

VEHICLE NO: GBE1397Z

CHASSIS/ENG.NO: JN1SC2F24Z0857249

VEHICLE MODEL: NISSAN CABSTAR

CLAIM NO: SNM21D207286/C02

POLICY NO:

REMARK 1397 TP CHINA AGST
GBD5683B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
				SUB-TOTAL:		0.00	
** NETT PRICE **							
1	1	PC	FRT BUMPER <i>sc</i>	1,185.10	10	1,039.59	1,039.59
2	1	PC	FRT CORNER PANEL LH <i>bt</i>	438.30	10	392.67	392.67
3	1	PC	FRT HEADLAMP LH <i>? Xnn</i>	518.50	10	466.65	466.65 X
4	1	PC	FRT DOOR LH <i>bt</i>	1,474.10	10	1,326.69	1,326.69
5	1	PC	FRT DOOR HINGE TOP LH <i>Xnn</i>	68.90	10	62.01	62.01 X
6	1	PC	FRT DOOR HINGE BOTTOM LH <i>Xnn</i>	68.90	10	62.01	62.01 X
7	1	PC	FRT DOOR CHECKER (LH) <i>Xnn</i>	48.20	10	43.38	43.38 X
8	1	PC	FRT DOOR LOWER SEAL LH <i>ne</i>	38.10	10	34.29	34.29
9	1	PC	FRT DOOR WEATHERSTRIPE LH <i>ne</i>	159.10	10	143.19	143.19
10	1	PC	FRT DOOR GLASS REGULATOR LH <i>? Xnn</i>	117.60	10	105.84	105.84 X
11	1	PC	FRT DOOR GLASS MOTOR LH <i>? Xnn</i>	568.10	10	511.29	511.29 X
12	1	PC	FRT DOOR SIGNAL LAMP LH <i>cm</i>	54.60	10	49.14	49.14
13	1	PC	FRT STEP GARNISH LH <i>cm</i>	151.10	10	135.99	135.99
				SUB-TOTAL		4,372.74	
** SPECIAL NETT PRICE **							
1	1	PC	ROC STICKER <i>ne</i>	20.00		20.00	20.00
				SUB-TOTAL		20.00	

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E&O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

TAIPING INSURANCE (SINGAPORE) PTE. LTD.

ANSON ROAD #16-00

PRINGLEAF TOWER SINGAPORE 079909

MOTOR CLAIMS DEPT

ATTENTION:

CONTACT: 62222366

FAX NO: 62221033

EST/QUOTE NO. SQ007049

DATE: 23/12/2021
ACCIDENT DATE: 14/12/2021
VEHICLE NO: GBE1397Z
CHASSIS/ENG.NO: JN1SC2F24Z0857249
VEHICLE MODEL: NISSAN CABSTAR
CLAIM NO: SNM21D207286/C02
POLICY NO:
REMARK: 1397 TP CHINA AGST GBD5683B

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** WORK LABOUR **							
			TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS				
			TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS				
			TO CHECK WIRING				
			TO APPLY ANTI RUST COATING				
			TO TRANSFER FRT DOOR GLASS LH COMPONENT				
				650.00	550	650.00	
				500.00	350	500.00	
				30.00		30.00	
				80.00	40	80.00	
				80.00	60	80.00	
				SUB-TOTAL			1,340.00
							1030

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey after repair

2802.51
10.00
1030.00
3842.51
206
3074.00

45-3,050

JOYCE

PAGE: 2 of 2

SUB-TOTAL: S\$ 5,732.74
ADD 7% GST: S\$ 401.29
GRAND TOTAL: S\$ 6,134.03

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause: