COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD3120B

Make

: HYUNDAI

Model : 1-40

Date: 16/12/2021

Insurance: NTUC

MVA: MS. YY

The last of the last	MVA: MS, Y Y				
Qty	Parts Description / Labour	Type	Unit Price	Amount	
	1 TAIL LAMP RH			\$697.80	101
	SUB TOTAL LESS 20%			\$925.80 \$185.16	
	DISCOUNTED TOTAL			\$740.64	
				\$^	Vett
	Labour Charge PANEL BEATING SPRAY PAINTING CHARGE CHECK ALL LIGHTING			\$150.00 ×	X N
	TOTAL LABOUR		-	\$60.00 7 \$310.00	1
	ESTIMATE TOTAL		=	\$1,050.64	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thruan elhhauto-lom
82235769
19/12/21 1630
LIS after rapair photo
10/194 wp

LKK Auto Consultants			
the Repairer of the follow			
 To resurvey before/after 	ung		
 To display damaged pr 	resurvey		
Parts prices are subi	ation		
 Third party survey 	at Prejudice" basis		
 No illegal modific 	bez		
 Supplementary 	resurveyed and		
is subject to line the	or insurance Company		
Acknowledge de rec			
Signature:			
Date:			