

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM21013013/Aty3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date	e: 17/01/2022	
	ATTN: LOH CYNTI	HIA	Cod	e: ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 8326R	Veh. Inspected	SNC 412M	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03OWY	Excess (\$)	0.00	
	Assign From	LOH CYNTHIA	Assign Date	22/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALPHARD HYBRID	c.c	2493	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	AYH300127932	Colour	BLACK	
	Odometer	21702 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
	L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
	R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
	L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	18/12/2021	Inspection Date	06/01/2022	
	Survey held at OOHRAY RENTAL PTE LTD				
	8 KAKI BUKIT AVENUE 4, #06-31, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				