

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

C.C. 125

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

) Site Insp (\$

) Interview (\$

) Tech. Invs (\$

) Weekend (\$

see note 05-08-2027 H1A 3847

14/1/22 H/S \$1550 informed MR 700

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

11/11

Name : Kho Bun Poo (85791668)

Accident Date : 15-Dec-21

Vehicle No : FBB7993D

Vehicle Model : Honda ANF
125MSS A

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Fork inner tubes <i>SUC</i>	\$ 280.00 <i>✓</i>
2	Fork outer tubes <i>11</i>	\$ 290.00 <i>✓</i>
1	Fork under bracker <i>11</i>	\$ 185.00 <i>✓</i>
1	Front sport rim <i>11</i>	\$ 280.00 <i>✓</i>
1	Front rim shaft <i>11</i>	\$ 42.00 <i>✓</i>
1	Front rim bearing <i>11</i>	\$ 38.00 <i>✓</i>
1	Front signal (1 set) <i>11</i>	\$ 130.00 <i>✓</i>
1	Side mirror (1 Set) <i>CUT O/S</i>	\$ 96.00 <i>✓</i>
1	Handle-bar <i>11</i>	\$ 80.00 <i>✓</i>
1 <i>O/S</i>	Handle bar ends <i>SUC</i>	\$ 95.00 <i>✓</i>
1	Hand grip (1 set) <i>11</i>	\$ 50.00 <i>✓</i>
1	Handle-bar inner cover <i>11</i>	\$ 128.00 <i>✓</i>
1	Headlamp <i>CNA</i>	\$ 160.00 <i>✓</i>
1	Front footrest bracket <i>nn</i>	\$ 55.00 <i>✓</i>
1	Front footrest rubbers <i>O/S TIAN</i>	\$ 56.00 <i>✓</i>
1	Brake pedal <i>BUT</i>	\$ 42.00 <i>✓</i>
2	Rear footrest <i>SUC</i>	\$ 76.00 <i>✓</i>
1	Rear footrest bracket <i>11</i>	\$ 130.00 <i>✓</i>
1	Rear taillamp <i>CNA</i>	\$ 88.00 <i>✓</i>
1	Rear fender <i>D/S</i>	\$ 68.00 <i>✓</i>
1	Rear sport rim <i>11</i>	\$ 380.00 <i>✓</i>
1	Rear rim shaft <i>11</i>	\$ 68.00 <i>✓</i>
1	Rear swing arm <i>11</i>	\$ 450.00 <i>✓</i>
1	Rear absorber <i>11</i>	\$ 320.00 <i>✓</i>
1	Main stand <i>11</i>	\$ 48.00 <i>✓</i>
1	Side stand <i>11</i>	\$ 58.00 <i>✓</i>
1	Exhaust assy <i>SO</i>	\$ 428.00 <i>✓</i>
1	Exhaust protector <i>BUT</i>	\$ 98.00 <i>✓</i>
1	Basket <i>11</i>	\$ 58.00 <i>✓</i>
1	Fairing assy <i>CNA</i>	\$ 485.00 <i>✓</i>
		\$ 4,762.00
Less 10%		\$ 476.20
		\$ 4,285.80

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Kho Bun Poo (85791668)

Accident Date : 15-Dec-21

Vehicle No : FBB7993D

Vehicle Model : Honda ANF
125MSS A

Estimated Repair Costs

Special Nett Items

1	Number Plate (1 set) <i>Front / Rear</i>	\$	38.00	<i>10</i>
2	Fork oils <i>11</i>	\$	30.00	<i>X</i>
2	Fork oil seals <i>11</i>	\$	56.00	<i>X</i>
1	Steering cone bearing (1 set) <i>11</i>	\$	85.00	<i>X</i>
1	Rear box <i>Daye</i>	\$	200.00	<i>180</i>
1	Rear box bracket <i>11</i>	\$	100.00	<i>X</i>
1	Sticker set <i>11</i>	\$	90.00	<i>✓</i>
		\$	599.00	

S/No. Labour

1	To provide towing (LOD)	\$	50.00	<i>✓</i>
2	To check wiring and reset headlamp focusing	\$	<i>11</i> 80.00	<i>X</i>
3	To repair body frame	\$	<i>11</i> 480.00	<i>X</i>
4	To provide labour	\$	420.00	
		\$	1,030.00	<i>300</i>

Grand Total

\$ 5,914.80

Singapore Dollars: Five Thousand Nine Hundred Fourteen and Cents: Eighty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.1473
102
1325.70
1985.70
202
1864