

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1031/2021/JT
DATE : 21-Dec-21
WIP : 59394

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 01 Mar 22

OWNER'S NAME : MS LIU YI
ADDRESS : 27 OXLEY WALK
#02-25
SINGAPORE 238596
TELEPHONE : HP +65 93377880
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700070654-04
VEHICLE NO : SLT 4377 P
MODEL CODE : AUDI S5 SB 3.0 TFSI
MODEL YEAR : 28/10/2017
ENGINE NO : CWG 042893
CHASSIS NO : WAUZZZF50JA037465
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Dec-21
PLACE OF ACCIDENT : CTE TOWARDS BUYONG ROAD
ENTRANCE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 4377 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,200.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,672.00	\$	2,272.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 4377 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,941.00	\$ 2,352.80
2	FRONT BUMPER FIXING PARTS	1	\$ 407.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 511.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 228.00	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 126.00	
7	RADIATOR GRILLE	1	\$ 3,508.00	\$ 2,806.40
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 102.00	
9	RADIATOR GRILLE UPPER COVER	1	\$ 189.00	
10	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 736.00	
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 124.00	
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 845.00	
13	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	
14	FRONT BUMPER TOP COVER	1	\$ 127.00	\$ 101.60
15	"CAUTION" STICKER	1	\$ 14.00	\$ 10.88
16	AIR COND STICKER	1	\$ 8.00	\$ 5.68
17	FRONT LOCK CARRIER BRACKET	1	\$ 137.00	
18	FRONT LOCK CARRIER SUPPORT - LH / RH	2	\$ 58.00	
19	POP RIVET	4	\$ 4.00	
20	HORN - RH	1	\$ 126.00	
SUB TOTAL SPARE PARTS		:	\$ 10,334.00	\$ 5,277.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 4377 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 5,277.36
21	HORN BRACKET - RH	1	\$ 29.00	
22	FRONT PARKING AID SENSOR - INNER / OUTER	2	TBC	
23	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	
24	BONNET	1	\$ 3,312.00	
25	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 84.00	
26	BONNET STRIKER - RH	1	\$ 50.00	
27	BONNET LOCK	1	\$ 214.00	
28	HEADLIGHT - RH	1	\$ 7,902.00	
29	LIFT CYLINDER - RH	1	\$ 198.00	
30	LIFT CYLINDER CORRUGATED PIPE	1	\$ 86.00	
31	RADIATOR AIR GUIDE RH - INNER / OUTER	2	\$ 47.00	
32	RADIATOR AIR GUIDE UPPER	1	\$ 16.00	
33	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
34	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 22,641.00	\$ 5,337.36
TOTAL LABOUR CHARGES			\$ 5,672.00	\$ 2,272.00
GRAND TOTAL			\$ 28,313.00	\$ 7,609.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-20/01/22