

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	18 Dec 2021 13:34	CIm Veh Model Changed		[] Merimen Administrator
2	18 Dec 2021 13:34	CIm Created	Reg No: SLT4377P. Policy No: 1700070654-04. Acct Date: 2021/12/17. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R21CI0002	[I] Merimen Administrator
3	23 Dec 2021 12:38	CIm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] NA MENG YAN
4	23 Dec 2021 12:38	Adj CIm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] NA MENG YAN
5	23 Dec 2021 12:38	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] NA MENG YAN
6	23 Dec 2021 12:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/03	[A] NA MENG YAN
7	23 Dec 2021 12:38	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] NA MENG YAN
8	23 Dec 2021 12:38	CIm Registration Modified	Rep:1137->200611.	[A] NA MENG YAN
9	23 Dec 2021 12:38	CIm Veh Model Changed	(202522) AUDI S5 SPORTBACK 3.0 TFSI QUATTRO (A).	[A] NA MENG YAN
10	23 Dec 2021 12:38	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] NA MENG YAN
11	23 Dec 2021 14:07	Adj Rpt Initiated		[A] HUEY YON
12	23 Dec 2021 14:07	CIm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
13	23 Dec 2021 14:07	CIm Dtl Modified	JPJ Reg. Date: -> 2017/10/28.	[A] HUEY YON
14	23 Dec 2021 14:07	CIm Details Notified		[A] HUEY YON
15	24 Dec 2021 10:22	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/03	[A] SHIAU CHAN
16	24 Dec 2021 10:23	Adj Mandate Request	Cur.Req:6163.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
17	27 Dec 2021 11:33	CIm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 2000.00. Excess Waived: -> 1000.00. 2F Rema rks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
18	27 Dec 2021 14:11	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/03. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after re	[I] Lim, Kok-Chong
19	27 Dec 2021 14:11	Adj Mandate Set	Approved:5840.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for a ll NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong
20	12 Jan 2022 12:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/03	[A] SHIAU CHAN
21	12 Jan 2022 12:02	Adj Mandate Request	Cur.Req:9253.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] SHIAU CHAN
22	13 Jan 2022 12:59	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/01/03. Mandate Remarks:	[I] Lim, Kok-Chong
23	13 Jan 2022 12:59	Adj Mandate Set	Approved:8930.00:	[I] Lim, Kok-Chong

Date From  **Date To**  **Audit Type**  **Go**

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2751530	23 Dec 2021 14:07:57	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLT4377P		11.00