

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/GRB21004991/R1tf3-1 Date: 23/12/2021 Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 8980M	Veh. Inspected	SLK 4432K
Policy No.	D21MFL0000447	Coverage (\$)	0.00
Claim No.	MFL2021D0001858	Excess (\$)	0.00
Assign From	CARINE KEK PHER SER	Assign Date	23/12/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/04/2021	Inspection Date	23/12/2021
Survey held at	EMPIRE IMAGE NO.4 PANDAN LOOP (BLK K / BLK 1) SINGAPORE 128222		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			