

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Dec 2021 14:30	Clm Veh Model Changed	(204880) TOYOTA SIENTA 1.5 X CVT (A).	[R] Ding Sing Hui, Kenneth
2	22 Dec 2021 14:30	Clm Created	Reg No: SLE7786B. Policy No: DMHCSNA00004192100. Acct Date: 2021/12/18. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Ding Auto Pte Ltd (HQ)	[R] Ding Sing Hui, Kenneth
3	22 Dec 2021 15:27	Clm Submitted	14785.34.	[R] Ding Sing Hui, Kenneth
4	22 Dec 2021 18:03	Clm Registration Modified	Excess: -> 2000.00.	[I] Adeline Chng Pei Wen
5	22 Dec 2021 18:03	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):please proceed to conduct OD survey and investigate further. Hirer mentioned about tire worn out and bald. Please assist to check whether tyre road worthiness meet minimum requirement?	[I] Adeline Chng Pei Wen
6	22 Dec 2021 18:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/31	[I] Adeline Chng Pei Wen
7	22 Dec 2021 18:03	Adj Mandate Set	Approved:0.00.	[I] Adeline Chng Pei Wen
8	22 Dec 2021 18:19	Assignment 1st Accessed		[A] NAMENG YAN
9	24 Dec 2021 20:08	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] DENISE TAY KWEE CHENG
10	24 Dec 2021 20:13	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	03 Jan 2022 15:32	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/12/31	[A] SHIAU CHAN
12	03 Jan 2022 15:32	Adj Mandate Request	Cur.Req:13794.34:OUR SURVEYOR CHECKED AND FOUND ALL TYRES IN SERVICEABLE CONDITION AND WITHIN LEGAL REQUIREMENT. PLEASE SEE PHOTOS UPLOADED. BRAKE & STEERING ALSO FOUND IN ORDER. PLEASE ADVISE SHOULD WE CONTINUE WITH INVESTIGATION.	[A] SHIAU CHAN
13	05 Jan 2022 16:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/31	[I] Pauline Tham
14	05 Jan 2022 16:33	Adj Mandate Set	Approved:13794.34.	[I] Pauline Tham

Date From 
Date To 
Audit Type

ACTIVITY
No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2751171	22 Dec 2021 14:30:50	OD/TP Case (Repairer)	Motor	Ding Auto Pte Ltd (HQ)	Ding Auto Pte Ltd (HQ)	SLE7786B		xx.xx
2751865	24 Dec 2021 20:13:48	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLE7786B		11.00