

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 21 Apr 2022

Preliminary Advice

Insured : SKQ7732E
Vehicle No
TP Vehicle : SMP2467K Accident Date : 21/12/2021
No
Make : TOYOTA NOAH HYBRID Assignment Date : 23/12/2021
Date of : 23/12/2021 Est. Duration of : 5
Inspection Repair
Inspection At : JWG INTERNATIONAL PTE LTD (HQ)
BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK
AUTOPOINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,762.93
Revised Amount	:S\$	7,520.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,520.16

Lump Sum Repair	:S\$	6,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.