

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : MSIG INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2112/012
Policy No:	PNMC202100004697	Date of Loss:	10/12/2021
Vehicle Reg. No.:	FBL1284D	Driveable?	yes
Driver Age:	22/06/1992	Third Party Vehicle No.:	GBG1661A
Any Injuries?	no	Contact No:	88080158
Insured/Claimant:	JONATHAN MITCHELL LEE MING JI	Driver:	JONATHAN MITCHELL LEE MING JI

PARTS MODEL

Make/Model:	Piaggio, GILERA RUNNER ST 200	Vehicle Reg. Date:	
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO GIA REPORT
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	5,241.02
Miscellaneous Items	330.00
Labour	1,000.00
Paintwork Labour	600.00
Towing	0.00
Gross Total(\$\$):	7,171.01
GST 7.00%(\$\$):	501.97
Nett Amount(\$\$):	7,672.98

This claim is handled by: Tee Shu yi

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	TRANSMISSION COVER <i>cut</i>	467.75	-10.00	420.98
2	1	COOLING COVER <i>cut</i>	88.10	-10.00	79.29
3	1	REAR LEFT PANEL <i>cut</i>	531.60	-10.00	478.44
4	1	REAR LEFT FOOT REST <i>BT</i>	383.10	-10.00	344.79
5	1	REAR LEFT FOOT REST BRACKET <i>BT</i>	234.60	-10.00	211.14
6	1	REAR RIGHT FOOT REST <i>cut</i>	383.10	-10.00	344.79
7	1	REAR RIGHT FOOT REST BRACKET <i>cut</i>	234.60	-10.00	211.14
8	1	REAR RIGHT PANEL <i>cut</i>	861.30	-10.00	775.17
9	1	STEP PANEL TOP GARNISH RH <i>cut</i>	415.80	-10.00	374.22
10	1	STEP PANEL RH <i>cut</i>	564.30	-10.00	507.87
11	1	STEP PANEL CHROME RH <i>cut</i>	282.10	-10.00	253.89
12	1	EXHAUST COVER <i>cut</i>	445.50	-10.00	400.95
13	1	STEP PANEL END RH <i>cut</i>	297.50	-10.00	267.75
14	1	SIDE MIRROR RH <i>cut</i>	178.20	-10.00	160.38
15	1	BRAKE LEVER <i>cut</i>	62.30	-10.00	56.07
16	1	FRONT FENDER <i>cut</i>	393.50	-10.00	354.15

Total Parts (\$\$) 5,241.02

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	VESPA EMBLEM <i>cut</i>	80.00	0.00	80.00
2	1	IU UNIT <i>cut</i>	250.00	0.00	250.00

Sub Total (\$\$) 330.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,000.00	0.00	1,000.00

Gross Labour Cost (\$\$) 1,000.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	0.00	600.00

Gross Labour Cost (\$\$) 600.00

< END OF ESTIMATES >

4 Days.
 Imps repair
 After repair photos.
 Gino Riccio - 82880282
 24/12/21