

22/11/2017 HSI 40701

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
24/11/17
1/5 \$900
2 days

VEHICLE No: SLH 1250D

1PC	REAR BUMPER
1SET	REAR BUMPER CLIPS
1PC	REAR BUMPER CHROME MOULDING
1PC	TAILLAMP N/S
1PC	REAR FENDER N/S

605.00

(102)

R	\$1,355.10	X
11	\$50.00	X
11	\$218.00	X
300	\$715.00	/
R	\$1,655.20	X
	\$3,993.30	

TO CHECK WIRING
TO DISMANTLE & REFIX REAR REVERSE SENSOR
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$40.00	20
	\$60.00	50
11	\$100.00	X
11	\$50.00	X
	\$680.00	300
	\$800.00	220
TOTAL	\$5,723.30	

605
102
P- 544.50
L- 590
1134.50
212
907

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: