



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21013098/Uvf3e2 Date: 11/01/2022 Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLQ 3188R	Veh. Inspected	FBS 911Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D17292201	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	24/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA AEROX GDR155	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MH3SG4640LJ071052	Colour	BLACK	
Odometer	32446 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110-70-14	PIRELLI	8 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120-70-14	PIRELLI	8 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/12/2021	Inspection Date	24/12/2021	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	