



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:YVONNE ANG

Ref: CC4/ASM21013104/Aea3q2
Date: 07/07/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5827M	Veh. Inspected	SGC 812A
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S1M03P8P	Excess (\$)	0.00
Assign From		Assign Date	24/12/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2050402R069332	Colour	BLUE
Odometer	45919 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	MICHELIN	6 mm
L/H Front Tyre	225/50 R17	MICHELIN	6 mm
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/12/2021	Inspection Date	24/12/2021
Survey held at	LC AUTOMOTIVE BLOCK 10 SIN MING IND.ESTATE , SECTOR C #01-20 SINGAPORE 575645		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------