

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No. EST0028494
Jason Ang Swee Kiat

Page 1 of 3
Your ref. TP-SBS 3372H MS FC
Job No. 72617
Our ref. 21.12.18
Payment
Date 23/12/2021

Attn:

Vehicle No. SMY 2233X
Vehicle Model Nissan Serena
Accident on 22/12/2021

Not with care
Heavy B4 pain
811711-17
5 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear windscreen <i>4015</i>	<i>shatter</i> 4,015.00	10.00	3,613.50 <i>✓</i>
1.00	Pc	Rear windscreen rubber	<i>in</i> 141.80	10.00	<i>me</i> 127.62 <i>✗</i>
1.00	Pc	Tailgate <i>1742</i>	1,742.00	10.00	<i>me</i> 1,567.80 <i>✓</i>
1.00	Pc	Tailgate handle moulding	<i>627-50</i> 797.20	10.00	<i>me</i> 717.48 <i>✓</i>
1.00	Pc	Tailgate chrome moulding <i>797-20</i>	797.20	10.00	<i>CM</i> 717.48 <i>✓</i>
1.00	Pc	Tailgate rubber	106.40	10.00	<i>in</i> 95.76 <i>✗</i>
1.00	Pc	Tail lamp LH	560.20	10.00	<i>CM</i> 504.18 <i>✓</i>
1.00	Pc	Rear bumper <i>1414</i>	1,414.00	10.00	<i>me</i> 1,272.60 <i>✓</i>
1.00	Pc	Rear bumper top garnish LH	384.60	10.00	<i>me</i> 346.14 <i>✓</i>
5.00	Pos	Rear bumper clips	5.00	10.00	<i>me</i> 22.50 <i>✓</i>
1.00	Pc	Rear bumper 'L' shape moulding	359.70	10.00	<i>in</i> 323.73 <i>✗</i>
1.00	Pc	Rear Highway Star emblem	60.90	10.00	<i>me</i> 54.81 <i>✓</i>
1.00	Pc	Rear E-Power emblem	79.90	10.00	<i>me</i> 71.91 <i>✓</i>
1.00	Pc	Rear Nissan logo emblem	<i>me</i> 79.90	10.00	<i>me</i> 71.91 <i>✗</i>
Special nett item:					
1.00	Pc	Rear bumper spoiler	1,000.00		<i>CM</i> 1,000.00 <i>✓</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确之测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

NRIC NO

SXXXX312H

Accident report SL0321CN0001

Page 1 of 15

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0028494
Jason Ang Swee Kiat

Page : 2 of 3
Your ref : TP-SBS 3372H MS FC
Job No : 72617
Our ref : 21.12.18
Payment :
Date : 23/12/2021

Attn :

Vehicle No : SMY 2233X
Vehicle Model : Nissan Serena
Accident on : 22/12/2021

611738.68

Quantity	Unit	Description	Unit price	Disc pct	Amount
		Labour & Misc			
1.00		Solar film + installation	350.00	(Bill)	350.00 ✓
1.00		To remove + renew rear windscreen	140.00		140.00 120 ✓
1.00		To supply sealant	40.00		40.00 ✓
1.00		To transfer rear reversing camera	60.00		60.00 ✓
1.00		To transfer rear view camera	60.00		60.00 50 ✓
1.00		To check/erase fault codes	60.00		60.00 X
1.00		To vacuum glass fragment	40.00		40.00 20 ✓
1.00		To straighten rear body, to knock dents on rear end panel and renew of parts	600.00		600.00 50 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENGE KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0028494
Jason Ang Swee Kiat

Page 3 of 3
Your ref TP-SBS 3372H MS FC
Job No 72617
Our ref 21.12.13
Payment
Date 23/12/2021

Attn

Vehicle No SMY 2233X
Vehicle Model Nissan Serena
Accident on 22/12/2021

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00		To spray paint	900.00		900.00

200h

Sub-Total 12,757.42
GST 7.00% 893.02
Total S\$ 13,650.44

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

NRIC No

 Accident report SL0321CN0001