

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI21013117/Ktf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 13/01/2022	
			Co	de: AGI	
1.	<u>_</u>				
	Insured Veh.	SMC 7500H	Veh. Inspected	SHD 9953A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013067/EE	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	27/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS (A)	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	JTDKB3FU703093449	Colour	M.P WHITE / RED	
	Odometer	76459 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	SAILUN	9 mm	
	L/H Front Tyre	195/65 R15	SAILUN	9 mm	
	R/H Rear Tyre	195/65 R15	DUNLOP	2 mm	
	L/H Rear Tyre	195/65 R15	DUNLOP	2 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/12/2021	Inspection Date	27/12/2021	
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD		
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: