

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI21013143/Avf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 23/05/2022	
			Cod	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFB 3344G	Veh. Inspected	SJX 8688R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013057/CD	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	27/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	BMW 528I	C.C	2996	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	WBAFS52000C276107	Colour	GREY	
	Odometer	119091 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55 R17	PIRELLI	6 mm	
	L/H Front Tyre	225/55 R17	PIRELLI	6 mm	
	R/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
	L/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/12/2021	Inspection Date	28/12/2021	
	Survey held at	N-51 AUTOMOTIVE PL			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	ia. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: