

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0028511
Yeong Chee Weng Peter

Page 1 of 1
Your ref. TP-SNA 7782J India
Job No. 72619
Our ref. 21.12.20
Payment
Date 27/12/2021

Not Authorized

*Re-survey B4 paint
6 days*

Attn: Mr. Weng Peter
Court Road

Vehicle No. SLN 3770A
Vehicle Model : Volvo V40
Accident on ... 25/12/2021

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front door LH	2,537.26		2,537.26 ✓
1.00	Pc	Rear door LH	2,469.17		2,469.17 ✓
1.00	Pc	Rear door rubber seal (upright) LH	165.77		165.77 ✓
1.00	Pc	Side skirt LH	646.69		646.69 ✓
Labour & Misc:					
1.00	hour	To check/erase fault codes after repair	120.00		120.00 ?
1.00	hour	To knock dents on front fender LH, rear side panel LH, rocker panel LH and renew of parts	1,000.00		1,000.00 750/
1.00	hour	To spray paint (including blending roof side panel LH)	1,500.00		1,500.00 1200/

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S\$ 9,029.61

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."