

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

SINGAPORE ACCIDENT STATEMENT

EST. No: EST0028511

Yeong Chee Weng Peter

Page 1 of 1
Your ref. TP-SNA 7782J India
Job No. 72619
Our ref. 21.12.20
Payment
Date 27/12/2021

Attn: Not Authorized

Vehicle No: SLN 3770A
Vehicle Model: Volvo V40
Accident on: 25/12/2021

Recovery B4 paint
87301.00 6 days

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Vehicle Registration: SLN3770A					
Supply of Parts - Nett item.					
1.00	Pc	Front door LH	2,537.26		2,537.26
1.00	Pc	Rear door LH	2,469.17		2,469.17
1.00	Pc	Rear door rubber seal (upright) LH	165.77		165.77
1.00	Pc	Side skirt LH	646.69		646.69
Labour & Misc:					
1.00	hr	To check/erase fault codes after repair	120.00		120.00
1.00	hr	To knock dents on front fender LH, rear side panel LH, rocker panel LH and renew of parts	1,000.00		1,000.00
1.00	hr	To spray paint (including blending roof side panel LH)	1,500.00		1,500.00
Private use					
No - Claiming					
Private car					
Auto					
1498					

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S\$ 9,029.51

公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。外, 还有先进的 SAICO Deluxe 喷漆烘炉。