

Re: Accident on 12/6/2017 involving SHD 6488X & SLP 284X - AIG (Our Ref: TAX/06/17/2081/lg)

Tan Lee Gek (Strides Automotive Services Pte Ltd) <LeeGek.Tan@strides.com.sg>

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Dear All,

We quantify our claim as follows:-

Cost of repairs \$480.00

Loss of rental \$170.94 (\$113.96 x 1½ days)

Loss of income \$ 90.00 (\$60.00 x 1½ days)

LTA search fee \$ 5.00

\$745.94

=====

We attach the proof of rental, repair bill, laid-up report, GIA report of our taxi and LTA search for your perusal.

Please let us hear from you soon.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV170600574
Date : 22.06.2017
Vehicle No. : SHD6488X
Your Ref No. : TAX/06/17/2081
Our Ref No. : 24090242
Terms : 30 Days

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
Parts					
BUMPER ASSY: REAR, FOR CHEVROLET EPICA	1.00	\$1238.00	(100.00)	\$1238.00	\$ 0.00
BRACKET RR BUMPER SIDE RH	0.00	\$ 49.00	(10.00)	\$ 0.00	\$ 0.00
Sub-Total					\$ 0.00
Labour					
TO REPAIR RH REAR PORTION	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
Others					
TO CHECK WIRING AND SYSTEM FUNCTION	0.00	\$ 80.00	0.00	\$ 0.00	\$ 0.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	1.00	\$ 140.00	0.00	\$ 0.00	\$ 140.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO REPLACE SUNDRY PARTS	1.00	\$ 20.00	0.00	\$ 0.00	\$ 20.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00
TO REPSRAY REAR BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
GRAND TOTAL					\$ 480.00

Remark :

Make/Model : CHEVROLET EPICA 2.0
Accident Date : 12.06.2017

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



Our Ref : TAX/06/17/2081/LG

Date : 06/07/2017

To : Claims Department

From : SMRT Taxis

ACCIDENT INVOLVING SHD6488X & SLP284X ON 12/06/2017 ALONG SIMS AVENUE


CONFIRMATION OF TAXI RENTAL

This is to confirm the daily taxi rental rate for taxi registration no. SHD6488X is \$113.96/day.

Kindly proceed to recover any rental loss from the third party as a result of this accident.

Thank you.

A circular stamp with 'SMRT TAXI PTE LTD' around the perimeter and a stylized 'S' in the center.
For Manager
SMRT Taxis Pte Ltd



Accident Vehicle Laid-Up Report

Registration No. : SHD6488X

Accident Case No. : TAX/06/17/2081

Make / Model : CHEVROLET EPICA 2.0

Ref. No. : 24090304

Date and Time Vehicle off-road for Accident Repair : 15.06.2017 08:19:32

Date and Time Repair Completed : 16.06.2017 13:42:42

Remarks :

Generated by : POHSUAN

Printed on : 19.06.2017

11/2

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	13 Jun 2017 / 08:16:47		
Asset Type:	Vehicle	Transaction Amount:	\$5.35
Asset ID:	SLP284X		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20170613081647903513

Search Date / Time: 12 Jun 2017 01:00:00

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Last updated on 11 Jun 2017 at 12:47 AM