

1 of 2 ?

100%

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref: CS/SMO21013201/Kqf3	
50 RAFFLES PLACE #03-03			Date: 28/12/2021	
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected SLX 9846Z		
Policy No.		Coverage (\$) 0.00		
Claim No. CMTD2103821/AGC		Excess (\$) 0.00		
Assign From GRACE TEO		Assign Date 28/12/2021		
2. Vehicle Particulars & Condition				
Make & Model		c.c 0		
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 23/12/2021		Inspection Date 28/12/2021		
Survey held at		S THREE AUTOMOTIVE & RECOVERY PTE LTD		
		BLK 8 SIN MING IND EST		
		#01-64/66		
		SINGAPORE 575643		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				