

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 17 March 2022 12:22 PM
To: 'Chan, Shu Hui Agnes'
Cc: SUR; Reports (LKKAUTO)
Subject: RE: Survey Report & Invoice of Vehicle SLX 9846Z Ref: CMTD2103821/AGC
Attachments: LKKAdjustment_Amended_.pdf; LKKInspection.pdf;
SMO_LKKInvoice_AC2201421.pdf; Resurvey Photo_1.pdf; LKKPhoto.pdf

Dear Agnes,

Enclosed herewith amendment report.

We have double check with our surveyor and he confirmed that he had finalised at Lump Sum \$6,300.00 with workshop.

Apologise for the confusion.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 15 March 2022 5:52 PM
To: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>
Cc: SUR <sur@lkkauto.com>; Reports (LKKAUTO) <report@lkkauto.com>
Subject: RE: Survey Report & Invoice of Vehicle SLX 9846Z Ref: CMTD2103821/AGC

Dear Agnes,

Thank you for the email.

We will check and revert to you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Reports (LKKAUTO) <report@lkkauto.com>
Sent: Tuesday, 15 March 2022 5:13 PM
To: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>
Cc: SUR <sur@lkkauto.com>; Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>
Subject: RE: Survey Report & Invoice of Vehicle SLX 9846Z Ref: CMTD2103821/AGC

Dear Agnes,

Thank you for your email.

Dear Shiao Chan,

Kindly assist.

Best Regards,

ELAINE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Shu Hui Agnes [<mailto:agnes.chan@sompo.com.sg>]

Sent: Tuesday, 15 March 2022 5:09 PM

To: Elaine (LKK Auto)

Cc: 'SUR'; 'Huey Yon (LKKAuto)'

Subject: FW: Survey Report & Invoice of Vehicle SLX 9846Z Ref: CMTD2103821/AGC

Dear LKK

The workshop/ S Three Automotive Recovery Pte Ltd repair bill stated repair cost at 6,300/-.

Please confirm whether the repair cost of SLX9846Z is 6,300/- or 6,200/-.

Thank you.

Working From Home with effect from 03 April 2020 till further notice.

Best Regards

Agnes Chan

Claim Divison

D: 6329 5327 | T: 6461 6555



SOMPO
INSURANCE

Innovation for Wellbeing

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Elaine (LKK Auto) <report@lkkauto.com>

Sent: Tuesday, March 15, 2022 4:54 PM

To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Cc: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; 'SUR' <sur@lkkauto.com>; 'Huey Yon (LKKAuto)' <hueyyon@lkkauto.com>

Subject: Survey Report & Invoice of Vehicle SLX 9846Z Ref: CMTD2103821/AGC

EXTERNAL SENDER: Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Agnes,

Enclose Survey Report of SLX 9846Z.

Thank you.

Best Regards,

ELAINE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)