

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Fiona Gan Bee Song

Date: 21 Jan 2022

Preliminary Advice

Insured	: YQ2996C		
Vehicle No			
TP Vehicle No	: JSD4117	Accident Date	: 11/12/2021
Make	: YAMAHA 135LC	Assignment Date	: 28/12/2021
Date of Inspection	: 29/12/2021	Est. Duration of Repair	: 4
Inspection At	: KIM KOCK MOTOR PTE LTD (HQ) BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,341.00
Revised Amount	:S\$	2,576.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,576.50

Lump Sum Repair	:S\$	2,050
-----------------	------	-------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.