



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21013228/Gqf3e2	
			Date: 03/01/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 91Y	Veh. Inspected	SMN 9256S
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/12/21/5024	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	28/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS PLUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTDZS3EU40J046536	Colour	GREY
	Odometer	194970 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	FIRENZA	6 mm
	L/H Front Tyre	205/60 R16	FIRENZA	6 mm
	R/H Rear Tyre	205/60 R16	FIRENZA	6 mm
	L/H Rear Tyre	205/60 R16	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/12/2021	Inspection Date	27/12/2021
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	