



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	:	UC293
Vehicle No.	:	SKU8870L
Make & Model	:	MERCEDES BENZ E200 CGI A

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	
3	To carried out repair on rear chassis member LH/RH	300.00	
4	Remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	100.00	
5	Airbag ECU resets and programming	300.00	
6	To carried out repair on connector and wiring system at accident damaged area and check for all electrical proper function	100.00	
7	Remove and replace undercarriage LH	200.00	
8	Remove and replace front cross member	300.00	
9	Remove and refit engine to facilitate repair	500.00	
10	Abs System coding and programming	300.00	
Labour Total :		4700.00	
TOTAL (PARTS & LABOUR):		35351.20	