



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/TP/1055/2021/JT
 DATE : 27-Dec-21
 WIP : 60344

Denise
\$6108.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/12/21

YOUR INSURED VEH NO : SMV 6275 P

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR SUBRAMANIAN BHASKARAN
 ADDRESS : BLK 636 JURONG WEST STREET 65
 #14-352
 SINGAPORE 640636
 TELEPHONE : HP +65 97366463
 TYPE OF CLAIM : THIRD PARTY CLAIM
 POLICY NO : MT/00899931
 VEHICLE NO : **SLA 4432 M**
 MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
 MODEL YEAR : 29/2/2016
 ENGINE NO : CZC 507710
 CHASSIS NO : WAUZZZ8V4G1056445
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 21-Dec-21
 PLACE OF ACCIDENT : JURONG WEST STREET 61

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX 6841 1183
 EMAIL: NORA.FHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 4432 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANFER REAR PARKINC AID. CHECK FUNCTION.	S/N \$ 280.00	✓ ✓
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$ 600.00	✗
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N \$ 400.00	✗
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	✗
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	✗
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN ATRRAG. FTC	S/N \$ 1,400.00	✗
SUB TOTAL LABOUR CHARGES		\$ 4,280.00	

Please see below for the final repair bill.
 Alastair
 92725127
 chwright@lkkkauto.com
 Your Ref: SKL 4817M
 Our Ref: CCA/AIG170194407R1p204



55 UBI ROAD, SINGAPORE 408699
 TEL: 6756 2323 FAX: 6841 1183

EMAIL: NORA.YHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 4432 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 4,900.00	2100 ✓
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$ 4,500.00	1400 ✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 13,872.00	

From: Haseo Tung (LKKAuto)
 Sent: Monday, 22 August 2018 12:28 PM
 To: nora.yhaaj@premiumauto.com.sg
 Subject: RE: ACCIDENT INVOLVING SLA 4432 M ALONG TRAVELOCK ROAD ON 30/08/2017
 Hi Mr Wee,
 We apologise for late reply.
 We are pending for condition from our insured on the matter and we get back to you as soon as possible.
 Machine of the AIG's reduction, we would like to request other repair charges of your vehicle for our condition.
 Thank you for your patience and understanding in the matter.
 Best regards,
 Haseo Tung (LKK Auto)
 LKK Auto (Singapore) Pte Ltd
 Phone: 6756 2323 / Email: nora.yhaaj@premiumauto.com.sg
 55 Ubi Road, Singapore 408699

PREMIUM AUTOMOBILES



55 DIBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2123 FAX: 6941 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 4432 M

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Deland</i>	1	\$ 2,070.00 ✓	✓	
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 193.00 +		
3	REAR BUMPER GUIDE SECTION - LH / RH <i>Not nec</i>	2	\$ 32.00 -	✗	
4	REAR BUMPER SPOILER <i>new</i>	1	\$ 237.00 ✗		
5	REAR LIGHT REFLECTOR - RH <i>Not nec</i>	1	\$ 41.00 ?	✗	
6	TAIL LIGHT - RH <i>new</i>	1	\$ 877.00 +		
7	TAIL LIGHT TRIM - RH <i>new</i>	1	\$ 30.00 +		
8	REAR BUMPER GUIDE SECTION OUTER - RH <i>Deland</i>	1	\$ 67.00 ?	✓	
9	REAR FENDER - RH <i>Repis</i>	1	\$ 4,140.00 ✗		
10	REAR WINDSCREEN <i>new</i>	1	\$ 814.00 +		
11	QUARTER WINDOW <i>new</i>	1	\$ 570.00 +		
12	PRIMER <i>new</i>	2	\$ 40.00 +		
13	REAR WHEEL HOUSING LINER <i>Not nec</i>	1	\$ 240.00 ?	✗	
14	REAR WHEEL SPOILER - RH <i>new</i>	1	\$ 35.00 +		
15	REAR WHEEL SPOILER COVER - RH <i>new</i>	1	\$ 4.00 +		
16	FUEL FILLER	1	\$ 89.00 +		
17	ARYLIC SEALANT <i>new</i>	S/N	\$ 180.00 +		
18	CAVIDY WAX <i>new</i>	S/N	\$ 140.00 +		
19	STONE CHIP	S/N	\$ 180.00 +		
20	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00 ✗		
SUB TOTAL SPARE PARTS			\$ 10,259.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

Regards
 Alastair
 92725127

Sent from my iPhone

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NDRA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


Subject:

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 4432 M

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	REMARKS
21	REAR WINDSCREEN SEALANT	S/N	\$	200.00	✓
22	1/4 GLASS SEALANT	S/N	\$	100.00	+
23	SUNDRIES		\$	400.00	? X
TOTAL SPARE PARTS		:	\$	10,959.00	
TOTAL LABOUR CHARGES		:	\$	13,872.00	
GRAND TOTAL		:	\$	24,831.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Handwritten notes:
 } MP
 } re
 MP re



Furthermore you reference to similar scenarios in MAG (Motor Accident Guide) (see below attached).
 Liability is largely against the party who is charging loss in this instance.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *29/10/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *AK Authorised, 05 Days*
H.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

JOHNNY BOO
BODY REPAIR MANAGER
Date:

Acknowledged by Repairer

ALLAN WU
CLAIMS CONSULTANT