



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21013244/Avf3e2 Date: 21/06/2022 Code: SMO	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKQ 1799C
Policy No.	D21MTPV01015092	Coverage (\$)	0.00
Claim No.	CMTD2103850/THE	Excess (\$)	700.00
Assign From	GRACE TEO	Assign Date	28/12/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2120362A955554	Colour	GREY
Odometer	153010 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R17	MICHELIN	6 mm
L/H Front Tyre	245/45 R17	MICHELIN	6 mm
R/H Rear Tyre	245/45 R17	MICHELIN	6 mm
L/H Rear Tyre	245/45 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/12/2021	Inspection Date	29/12/2021
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		
5a. Remarks			
A)THE MARKET VALUE IS S\$75,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	