

06/01/22@5.09pm revised to Lorriance by email.

The U/C / Chassis frame / Body Structure affected due to collision.

TOTAL

REPAIR ESTIMATE

DATE: 29.12.21

3P INSURANCE: SOMPO

(45)

MODEL: HYUNDAI I40

SURVEYOR: NA

VEH NO.: SHD3216J

MVA: LIM T S

not Arthur
Lan
marcus
29/12/21
marcus@lkk
auto.com
Sdy.
Zurich Wtff.ry.
e 12.30pm

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid <i>sent / sent</i>	1		\$2,609.80
	Bootlid Hinge (LH/RH) <i>R</i>	2	\$142.30	284.60 X
	Bootlid 'H' Emblem <i>new</i>	1		\$28.70
	Bootlid CRDI Plate <i>new</i>	1		\$27.90
	Bootlid I40 Emblem <i>new</i>	1		\$27.90
	Bootlid Moulding <i>sent</i>	1		\$85.00
	Bootlid Lower Outer Garnish <i>one</i>	1		\$227.90
	Rear Bumper <i>P.S</i>	1		\$553.00
	Rear Bumper Reinforcement <i>one</i>	1		\$428.40 ?
	Rear Bumper Clip (10 pcs) <i>new</i>	10	\$2.20	\$22.00
	Rear Bumper Side Bracket RH/LH <i>new</i>	2	\$35.60	\$71.20
	Rear Bumper Sponge <i>trim</i>	1		\$119.50
	Rear Bumper Under Cover <i>new</i>	1		\$228.00
	Exhaust Muffler RH <i>R</i>	1		\$967.70 X
	Exhaust Centre Pipe <i>R</i>	1		\$730.10 X
	Rear End Panel <i>DD</i>	1		\$526.70
	Rear End Panel Garnish <i>trim</i>	1		\$57.70
	Rear End Lower Panel <i>R</i>	1		\$495.50 X
	Bootlid Lamp RH / LH <i>o/sone n/sone</i>	2	\$622.20	\$1,244.40 RH LPC
	Taillamp RH / LH <i>one</i>	2	\$697.80	\$1,395.60
SPARE PARTS SUB TOTAL				\$10,131.60
Less 20% LESS 20%				\$2,532.90
DISCOUNTED TOTAL				\$7,598.70
				8105.28
	Bootlid ComfortDelGro <i>new</i>	1		\$30.00
	Bootlid 65521111 <i>new</i>	1		\$30.00
	Reverse Sensor <i>small</i>	1		\$135.70
	Rear No. Plate With Trim Cover <i>sent</i>	1		\$55.00 20
	Rear Bumper Mat <i>P.S</i>	1		\$50.00
NETT TOTAL				\$300.70
SPARE PARTS & OTHERS TOTAL				\$7,899.40
	Panel Beating <i>280</i>			\$900.00
	Spray Painting Charge <i>200</i>			\$900.00
	Check Lightings			\$40.00
	Tuff Kote			\$40.00
	Remove/Refix Reverse Sensor			\$120.00
	Remove/Refix Exhaust System			\$100.00
LABOUR TOTAL				\$2,100.00
ESTIMATE TOTAL				\$9,999.40
				10505.98

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Supplementary items must be recorded and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD3216J
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Dec 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	D4FDGU650729
Chassis No.:	KMHLB41UMGU091349
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$19,074.00
Original Registration Date:	09 Jun 2016
First Registration Date:	09 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,074.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jun 2024
PARF Rebate Amount:	\$13,351.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$11,354.00
Total Rebate Amount:	\$24,705.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Dec 2021

OK

Date/Time: 29.12.2021 08:52 Page : 1

Am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4157161

JC NO 305499539

OWNER
S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)
(P)

OUNT CARD NO.


REGN NO. SHD3216J	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE/TIME IN 28.12.2021 13:10
YR OF MANU 09.06.2016	TARGET DATE
CHASSIS CODE KMHLE41UMGU091349	COMPLETION DATE/TIME

cident Date: 28.12.2021
TURE: 3P 28.12.2021

JOB DESCRIPTION

NO
0010 LABOR CODE
PB

DESCRIPTION
LUMPSUM REPAIR-SHD3216J



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER S SIGNATURE

edgement Slip

Exit Pass

to: SHD3216J

LIMITS

Vehicle No.: SHD3216J

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard