

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Dec 2021 17:40	Clm Veh Model Changed	(205699) HONDA HR-V 1.5 DX CVT (A).	[R] Wee Tien Lung
2	28 Dec 2021 17:40	Clm Created	Reg No: SLR3584A. Policy No: MPC21P00150000. Acct Date: 2021/12/24. Claim Type: OD. Insurer: ECICS Limited (HQ). Workshop: Wah Hong Motors & Credit Pte Ltd (HQ)	[R] Wee Tien Lung
3	28 Dec 2021 17:48	Clm Submitted	1314.50.	[R] Wee Tien Lung
4	29 Dec 2021 12:33	Clm Registration Modified	Excess: -> 0.00. Excess Waived: -> 500.00.	[I] Crystabelle Tan
5	29 Dec 2021 12:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: ECICS EXT ADJ - OD/TP. Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Crystabelle Tan
6	29 Dec 2021 12:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/07	[I] Crystabelle Tan
7	29 Dec 2021 12:33	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Crystabelle Tan
8	29 Dec 2021 14:08	Assignment 1st Accessed		[A] CELINE FONG
9	29 Dec 2021 14:25	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
10	31 Dec 2021 10:52	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	31 Dec 2021 10:55	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/07	[A] DENISE TAY KWEE CHENG
12	31 Dec 2021 10:58	Adj Mandate Request	Cur Req:1094.50:DAMAGE CONSISTENET REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
13	31 Dec 2021 11:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/07	[I] Liu Chun Cheong
14	31 Dec 2021 11:55	Adj Mandate Set	Approved:1094.50.	[I] Liu Chun Cheong

Date From
 Date To
 Audit Type

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2752739	28 Dec 2021 17:40:27	OD/TP Case (Repairer)	Motor	Wah Hong Motors & Credit Pte Ltd (HQ)	Wah Hong Motors & Credit Pte Ltd (HQ)	SLR3584A		xx.xx
2752740	28 Dec 2021 17:42:52	CMF LITE (OD)	TrueSight-CMF	ECICS Limited (HQ)	ECICS Limited (HQ)	SLR3584A	RASHIDAH BINTE ALLAPITCHAY MOH	xx.xx
2753515	31 Dec 2021 10:52:30	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLR3584A		11.00

