

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	932A
Vehicle Details	
Vehicle No.:	SMG2822R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Dec 2021
Vehicle Make:	PEUGEOT
Vehicle Model:	308 5DR ALLURE PURETECH 1.2 A/T 2WD
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	10XTA40963036
Chassis No.:	VF3LPHNYWJS089855
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,283.00
Original Registration Date:	13 Dec 2018
First Registration Date:	13 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$21,797.00 10898
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2028
PARF Rebate Amount:	\$16,347.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,000.00
COE Rebate Amount:	\$17,379.00
Total Rebate Amount:	\$33,726.00

The information contained herein is correct as at 29 Dec 2021

OK



LK Auto Consultant ZOOM AUTOWERKS PTE LTD

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Acknowledged by Repairer

Signature:

Date:

31 December 2021

REG NO.: SMG 2822 R
MAKE/MODEL: PEUGEOT 308

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen inner seal	\$ 11 85.00 X
1	Rear tailgate	\$ 11 1,450.00 X
1	Rear tailgate inner lock	\$ 11 245.00 X
1	Rear tailgate logo	\$ 11 85.00 X
1	Rear tailgate rubber	\$ 11 146.00 X
1	Rear tailgate "PEUGEOT" emblem	\$ 11 68.00 X
1	Rear tailgate "308" emblem	\$ 11 65.00 X
2	Rear taillamps	\$ 11 1,172.00 X
1	Rear end panel	\$ R 865.00 X
1	Rear end panel inner garnish	\$ 11 192.00 X
1	Rear end panel air vent	\$ 11 42.00 X
1	Rear bumper	\$ 945 50/nop 1,065.00
2	Rear bumper brackets	\$ 11 156.00 X
1	Rear bumper clip (1 set)	\$ 50 60.00
1	Rear bumper lower diffuser	\$ 2 425.00
1	Rear bumper reinforcement	\$ 585 685.00
2	Rear bumper side retainers	\$ 11 130.00 X
1	Rear bumper tow hook cover	\$ 11 28.00 X
		\$ 6,964.00
	Less 10%	\$ 696.40
		\$ 6,267.60

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 11 80.00 X
1	Rear reverse sensor (1 set)	\$ 800 350.00 X
		\$ 430.00

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 150.00 60
3	To remove and refit rear reverse sensor.	\$ 150.00 50
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 11 120.00 X
5	To remove and refit rear windscreen glass.	\$ 11 180.00 X
6	To apply undercoating.	\$ 11 200.00 X
7	Panel beating.	\$ 1,500.00 300
8	To re-spray painting on the affected areas.	\$ 1,400.00 400
		\$ 3,780.00

GRAND TOTAL :

\$ 10,477.60