

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

28/12/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SJJ1365U

Veh Model :- TOYOTA ALLION 1.5 A

Estimate# :- CK422682

Claim # :-

ACC. Date :- 24/12/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN GLASS MOULDING <i>nee</i>	1	168.00	168.00 ✓
2.	REAR FENDER RH <i>blu</i>	1	1,350.00	1,350.00 ✓
3.	REAR FENDER INNER TRIM RH <i>de</i>	1	385.00	385.00 ✓
4.	REAR FENDER COWLING RH <i>xnn</i>	1	55.00	55.00 X
5.	REAR FENDER AIR DUCT RH <i>xnn</i>	1	135.00	135.00 X
6.	TAILLAMP ASSY RH <i>cr</i>	1	315.00	315.00 ✓
7.	TAILLAMP PANEL RH <i>xnn</i>	1	115.00	115.00 X
8.	TAILLAMP CLIPS <i>ne</i>	2	8.90	17.80 ✓
9.	REAR END PANEL (REPAIR) <i>xnn</i>	1		
10.	REAR BUMPER <i>de</i>	1	555.00	555.00 ✓
11.	REAR BUMPER RETAINER RH <i>xnn</i>	1	75.00	75.00 X
12.	REAR BUMPER CLIPS <i>ne</i>	10	5.50	55.00 ✓
13.	REAR SHOCK ABSORBER RH - CHECK <i>xnn</i>	1		
LIST TOTAL S\$				3,225.80
25% DISCOUNT S\$				-806.45
				2,419.35
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN GLASS SEALANT	1	40.00	40.00 ✓
SPECIAL NET TOTAL S\$				40.00
LABOUR :				
TO CUT/WELD REAR FENDER RH, TAILLAMP PANEL RH REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				
SPRAY PAINT REAR FENDER RH, TAILLAMP PANEL RH, REAR END PANEL, REAR FENDER INNER PANEL RH, REAR BUMPER				
REMOVE & REPLACE REAR WINDSCREEN & CHECK WATER LEAKAGE				
REMOVE & REPLACE REAR SPEAKER BOARD, REAR SEAT ASSY, REAR FLOOR CARPET, UPHOUSTERY				
REMOVE & REPLACE REAR UNDER CARRIAGE . SUSPENSION				
COMPUTER WHEEL ALIGNMENT				
LABOUR TOTAL S\$				2,320.00

2595.80

259

1946.85

40

1200 } 600 1,000.00
400 800.00
120.00
80 160.00
nn X 180.00
nn X 60.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

28/12/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 143308

Veh # :- SJJ1365U

Veh Model :- TOYOTA ALLION 1.5 A

Estimate# :- CK422682

Claim # :-

ACC. Date :- 24/12/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 4,779.35

GST @ 7 % 334.55

AMOUNT DUE S\$ 5,113.90

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1946.85

40.00

1200.00

3186.85

20%

2549.48

L/s - \$ 2,550 / 5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid

Hp 900 10068

5 days

L/s

29/12/21 @ 1645

Resurvey after repair