

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. BP 5247	Date Estimated 26/11/2021	Page No. 1 of 3
	Prepared By Clement Chia Cher-Yang	

ESTIMATE REPAIR FOR	ACCOUNT 14508
Li Xiaowen 25 Fernvale Lane #11-36 Singapore 797502	Liberty Insurance Pte Ltd 51 Club Street #03-00 Liberty House Singapore 069428

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB1510K	VF3MRHNSUMS131835	28/06/2021	3008 1.2 Active Prem	7670

DESCRIPTION	VALUE
TO CONDUCT OD CLAIM AGAINST LIBERTY INS. DOA:24.11.2021	0.00
TO REMOVE & REPLACE FRT BUMPER, FRT BONNET, REAR BUMPER, REAR TAILGATE & ALL OTHER ACCIDENT AFFECTED PORTIONS. @600	2400 3,000.00
TO REMOVE/INSTALL FRT RADIATOR, COOLING FAN HOUSING, CONDENSER & ALL NECESSARY PARTS TO FACILITATE REPAIR INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM, CHECK FOR LEAKS & REFILL GAS.	600.00
TO RECONNECT ALL ELECTRICAL COMPONENTS, CONTROL UNITS/MODULE & WIRINGS AT FRT SECTION INCLUDING CHECKS FOR PROPER FUNCTION & ADJUSTMENT OF HEADLAMPS	150.00
ACCIDENT TOWING receipt	140.00
TO SPRAY PAINT FRT BUMPER, FRT BONNET, REAR TAILGATE & ALL OTHER AFFECTED AREAS @600	2,400.00
TO CONDUCT BODY CAVITY PRESERVATIONS.	120.00
TO SUPPLY & INSTALL FRONT NUMBER PLATE WITH FRAME	70.00
TO SUPPLY & INSTALL 3M FILM FOR REAR TAILGATE WINDOW	350.00
TO REMOVE & REPLACE REAR TAILGATE WINDOW GLASS & CONDUCT WATER LEAK TEST.(NETT)	600.00
TO CONDUCT RE-PROGRAMMING & RESETTING OF ECU SYSTEM INCLUDING CLEARING OF FAULT CODES.(NETT)	600.00
SUNDRIES	30 100.00
Total Labour 1:	8,130.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
9838520180	RADIATOR NEW	1	655.00	10.00	589.50
9836058380	MOTOR-DRIVEN FAN	1	655.00	10.00	589.50
9827450180	CONDENSER	1	1,150.00	10.00	1,035.00
9827917380	PARKING SENSOR	4	180.00	10.00	648.00
9827917380	PARKING SENSOR	4	180.00	10.00	648.00
1636403680	REAR BUMPER	1	750.00	10.00	675.00
168008801T	CENTRAL STRIP, BPR/R	1	413.00	10.00	371.70
1618040780	OVERRIDE - RH REAR BUMPER	1	276.00	10.00	248.40
1618040880	OVERRIDE - LH REAR BUMPER	1	276.00	10.00	248.40

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE



Estimate No.	Date Estimated	Page No.
BP 5247	26/11/2021	2 of 3
Prepared By Clement Chia Cher-Yang		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB1510K	VF3MRHNSUMS131835	28/06/2021	3008 1.2 Active Prem	7670

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1618040980	RECESS DOOR-REAR BUMPER (TOW HOOK) <i>de</i>	1	55.00	10.00	49.50
9811280580	BRACKET - CENTRAL REAR BUMPER <i>Xan</i>	1	120.00	10.00	108.00
9816071580	REINFORCEMENT - REAR BUMPER <i>bt</i>	1	490.00	10.00	441.00
1617409480	TAILGATE ASSY <i>cut</i>	1	2,680.00	10.00	2,412.00
9810847380	TAILGATE GLASS <i>photo</i>	1	630.00	10.00	567.00
873598	SHIM GLASS <i>ne</i>	6	1.00	10.00	5.40
981257362D	LINING INNER - REAR PANEL <i>Xan</i>	1	270.00	10.00	243.00
98377912DX	REAR EMBLEM <3008> <i>ne</i>	1	35.00	10.00	31.50
98377914DX	FRONT EMBLEM <3008> <i>ne</i>	1	35.00	10.00	31.50
98377943DX	FRONT BADGE <LION> <i>ne</i>	1	68.00	10.00	61.20
983679311T	MOULDING TOP-FRONT BUMPER <i>cm</i>	1	620.00	10.00	558.00
1675868380	FRONT BUMPER <i>de</i>	1	1,275.00	10.00	1,147.50
983677021T	RECESS DOOR/F <i>ne</i>	1	64.00	10.00	57.60
9836837880	RAD GRIL BRACKT SUP <i>cm</i>	1	450.00	10.00	405.00
98367693TN	GUARD GRILLE SUP <i>cm</i>	1	405.00	10.00	364.50
1675868580	FINISHER BUMPER/F <i>dis</i>	1	510.00	10.00	459.00
1675868180	PLUG, BPR/F <i>cm</i>	1	112.00	10.00	100.80
1675867980	PLUG, BPR/F <i>cm</i>	1	270.00	10.00	243.00
983682721T	MOULDING TOP-FRT BUMPER LWR MLDG <i>mis</i>	1	280.00	10.00	252.00
1675868280	MOULDING-FRT LOWER BUMPER <i>de</i>	1	410.00	10.00	369.00
98367683XT	GUARD GRILLE INFERIEUR <i>cm</i>	1	263.00	10.00	236.70
98367957XT	PLUG, BPR/F <i>cm</i>	1	80.00	10.00	72.00
9836769980	BUMPER/F ABSORBER <i>Xan</i>	1	170.00	10.00	153.00
98106346XT	BUMPER BRACKET <i>cm</i>	1	260.00	10.00	234.00
9822100180	BUMPER ABSORBER/F <i>Xan</i>	1	332.00	10.00	298.80
9824513780	REINFORCEMENT REAR-FRT BUMPER <i>Xan</i>	1	580.00	10.00	522.00
9842375180	ENGINE BONNET ASSY <i>bt</i>	1	1,880.00	10.00	1,692.00
9814189880	BONNET HINGE LH <i>Xan</i>	1	190.00	10.00	171.00
9814188880	BONNET HINGE RH <i>Xan</i>	1	190.00	10.00	171.00
9830070480	BONNET LOCK <i>Xm</i>	1	35.00	10.00	31.50
9820277480	BONNET PROP <i>Xan</i>	1	40.00	10.00	36.00
9827085980	HOOD HOOK <i>Xan</i>	1	60.00	10.00	54.00
9837133180	DEFLECTOR <i>cm</i>	1	120.00	10.00	108.00
9824055880	FRONT FACE CROSSMEMBER <i>Xan</i>	1	205.00	10.00	184.50
98114500XT	BUMPR DEFLECTOR <i>cm</i>	1	235.00	10.00	211.50
9812305780	FRONT WING LH ASSY <i>Xm</i>	1	450.00	10.00	405.00
9812305680	FRONT WING RH ASSY <i>Xan</i>	1	450.00	10.00	405.00
98252889XT	WING MOULDING LH <i>Xan</i>	1	228.00	10.00	205.20
98252888XT	FRONT WING MOULDING RH <i>Xan</i>	1	228.00	10.00	205.20
98365912XT	WING MOULDING LHR <i>Xan</i>	1	230.00	10.00	207.00
98365911XT	WING MOULDING RHR <i>Xan</i>	1	230.00	10.00	207.00
9836230980	FRONT LIGHT RH <i>cm</i>	1	360.00	10.00	324.00
9836231080	FRONT LIGHT LH <i>Xan</i>	1	360.00	10.00	324.00
1675889680	HEADLAMP RH <i>cm</i>	1	1,404.00	10.00	1,263.60
1675889780	HEADLAMP LH <i>cm</i>	1	1,404.00	10.00	1,263.60

TOFRANCE

Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159042, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. BP 5247	Date Estimated 26/11/2021	Page No. 3 of 3
Prepared By Clement Chia Cher-Yang		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB1510K	VF3MRHNSUMS131835	28/06/2021	3008 1.2 Active Prem	7670

Total Parts : **21,945.60**

Rasul
Hp 90010068
7 days
29/12/21 @ 1500
Resur before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Customer Name & Signature / Company Stamp	Labour 1	S\$	8,130.00
	Parts	S\$	21,945.60
	Labour 2	S\$	0.00
	Excess	S\$	0.00
	Total GST @ 7%	S\$	2,105.29
	Grand Total	S\$	32,180.89

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

Business Registration No. 53055563L GST Registration No. M2-0000551-1

Tel: 64777409 Fax: 64777398



Date: 7/2/2022

Parts Total:	\$4,989.15
---------------------	-------------------

Total Labour:	\$1,200.00
Total Parts & Labour:	\$6,189.15
GST @ 7%:	\$433.24
Grand Total:	\$6,622.39

17/03/22

Raised By Technician	Approved By CSA CLEMENT	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	-----------------------------------	-----------------------------------	--------------------------------------