

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

30-Dec-21

Our ref : TP/5073/21

Polaris International (S) Pte Ltd

TP Sampo.
veron.

RE : estimate cost for vehicle no : GBF 4779E

1 pc	frt rh wing mirror	Missing	\$	151.00	✓	
1 p[c	frt rh wing mirror bracket	Best		228.00	✓	1738
1 pc	frt rh signal lamp	anked		193.00	✓	
1 pc	rh headlamp	anked		716.00	✓	1477.30
1 pc	frt rh corner panel	Rys		214.00	✓	
1 pc	frt rh door	Rys		1,160.00	+	
1 pc	frt rh door glass	lit		560.00	+	450
				3,222.00		
			less 15%	483.30		
				2,738.70		
1 pc	body sticker	3 x 1m		25.00	snett ✓	225
1 pc	Company logo			300.00	200	
Panel beating.				800.00	400	
Spray painting.				800.00	400	
Transfer door parts.				80.00	+	870
Remove & refit rh door glass.				80.00	40	
Wiring.				30.00	✓	
				4,853.70		
			Plus 7% GST	339.76		
				5,193.46		

SD : Five thousand one hundred ninety-three & cents forty-six only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan
h/s 31/12/21
03 Day
total: 2572.30
y/s 21c