

TP Chinn.  
Xiao Chen.

SMX557IE. 2015 August.

Nissan Qashqai 1197cc

SJNFEAJ11U1425489.

|                                  |          |                  |       |
|----------------------------------|----------|------------------|-------|
| Front Number Plate               | 2        | 30(SN)           | X     |
| Front Number Plate Holder        | 2        | 30(SN)           | X     |
| Front Bumper                     | Deformed | 689.80           | /     |
| Front Bumper Clips               | 12       | 30(SN)           | /     |
| Front Bumper Side Holder x 2     | 2        | 25.9 x 2 = 51.80 | 25.90 |
| Front Bumper Tow Cover           | 1        | 28.20            | X     |
| Front Bumper Reinforcement       | Dented   | 457.70           |       |
| Front Bumper Reinforcement Lower | 1        | 337.30           | X     |
| Front Bumper Sponge              | Crushed  | 195.70           | /     |
| Front Bumper Fog Lamp LH.        | Crushed  | 279.70           | /     |
| Front Bumper Fog Lamp Cover LH.  | Crushed  | 102              | /     |
| Front Bumper Lower Garnish       | Crushed  | 284.80           | /     |

Sm X 5571E.

|                                    |                 |                      |     |
|------------------------------------|-----------------|----------------------|-----|
| Front Grille                       | cracked         | 461.20               | ✓   |
| Front Grille Chrome Moulding       | rip             | 160.80               | X   |
| Front Grille Logo.                 | rip             | 109.20               | ✓   |
| Front Grille Clips.                | rip             | 20(SN)               | ✓   |
| Headlamp LH.                       | cracked         | <del>2961</del> 1617 |     |
| Front LH Fender.                   | Repair          | 622.70               | X   |
| Front LH Fender Arc Garnish        | cracked         | 483                  | ✓   |
| Front LH Fender Arc Garnish Clips. | rip             | 20(SN)               | ✓   |
|                                    | 4705.50         |                      |     |
|                                    | 4234.95         | S.N. 70              |     |
| Panel Beating                      | <del>800.</del> | 400                  |     |
| Spray Painting.                    | <del>800.</del> | 400                  |     |
| Wiring.                            | <del>50.</del>  | 30.                  | 830 |

total: 5134.55

U/S: A.I.K.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: