

00

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 30 Dec 2021

ASSESSMENT FOR REPAIR: YAMAHA GDR155A AEROX - FBP9311K

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Wheel axle	\$65.00*
1 pc	Left fork assy	\$405.00*
1 pc	Steering stem	\$220.00*
2 pcs	Steering stem bearings @ \$45.00	\$90.00*
1 pc	• Handle bar	\$165.00 <i>? bt</i> ✓
1 pc	Left view mirror	\$45.00 <i>cut</i> ✓
1 pc	Left rear foot rest	\$45.00 <i>cut</i> ✓
1 pc	Brake lever left	\$48.00 <i>cut</i> ✓
1 pc	Balancer left	\$40.00 <i>cut</i> ✓
1 pc	• Centre cover inner body	\$195.00 <i>? dl</i> ✓
1 pc	Centre cover lower	\$140.00 <i>cut</i> ✓
1 pc	• Left footstep	\$185.00 <i>x all</i> ✓
1 pc	Body coverset decals	\$125.00 <i>cut</i> ✓
1 pc	Body coverset	\$495.00 <i>cut</i> ✓
1 pc	Airbox assy	\$195.00 <i>cut</i> ✓
1 pc	NVX amblem	\$35.00 <i>cut</i> ✓
1 pc	Mainstand	\$145.00 <i>bt</i> ✓
1 PC	LEFT ENGINE COVER	\$135.00 <i>cut</i> ✓
	Less discount 10%	\$2,638.00 \$263.80 \$2,374.20
	<u>Special nett items</u>	
1 pc	Box rack	\$195.00 <i>cut</i> ✓
1 pc	Top box	\$280.00 <i>cut</i> ✓
1 pc	Front sport rim	\$350.00*
1)	Towing charges	\$100.00 <i>? towing receipt.</i>
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 <i>300.</i>
3)	To remove, replace and balance front wheel rim	\$120.00*
4)	To knock, straighten chassis & body balancing	\$380.00*

60

120? parts

\$180.00

5)

To remove/refit, replace (if damage) check and straighten front fork tubes.

Total Estimate

\$4,679.20

Note: The above estimate is subjected to the prevailing GST of 7%



Taufik 97495749

'wp' 14/1/21 @ 515pm

3 days

Taufik @ Whatsapp

1/3 Resing after repair

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 17 Jan 2022

SUPPLEMENTARY FOR REPAIR: YAMAHA GDR155A AEROX - FBP93111

Chassis No.:
Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left footstep lower	\$115.00 <i>cut</i>
		<hr/>
		\$115.00
	Less discount 10%	\$11.50
		<hr/>
		\$103.50
	<u>Special nett items</u>	

Total Estimate

\$103.50

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

[Handwritten signature]

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 19 Jan 2022

SUPPLEMENTARY FOR REPAIR: YAMAHA GDR155A AEROX - FBP9311K

Chassis No.:


Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Headlamp assy / BR	\$345.00
		<hr/>
	Less discount 10%	\$345.00
		\$34.50
		<hr/>
	<u>Special nett items</u>	\$310.50

Total Estimate

\$310.50

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

Guo Qifeng

