

**ESTIMATE TO REPAIR**

VEHICLE NO. : SML 1211 J  
 MAKE : HONDA  
 MODEL : FIT 1.3 GF CVT  
 YEAR : 2019  
 CHASSIS NO : GK31346914

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 28-Dec-21  
 DATE OF ACCIDENT : 27-Dec-21  
 THIRD PARTY REF : SMB 3005 C  
 TOWER TRANSIT

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper				\$ 529.60
2 pcs	rear bumper retainer		\$ 18.70		\$ 37.40
10 pcs	rear bumper clips		\$ 3.50		\$ 35.00
1 pc	rear end panel				\$ 341.60
1 pc	rear end panel garnish				\$ 71.60
1 pc	rear space tyre top cover				\$ 229.90
1 pc	rear space tyre sponge				\$ 146.60
1 pc	tail gate				\$ 885.80
1 pc	tail gate lock				\$ 188.40
1 pc	tail gate rubber				\$ 92.30
1 pc	tail gate outer handle				\$ 112.30
1 pc	H emblem				\$ 24.70
1 pc	fit emblem				\$ 30.50
1 pc	tail gate trim				\$ 171.30
1 pc	rear windscreen moulding				\$ 118.50
1 pc	rear wiper arm				\$ 58.00
1 pc	rear wiper arm cap				\$ 12.00
1 pc	rear wiper blade				\$ 43.20
1 pc	rear wiper motor				\$ 225.00
	Less 20%				\$ 3,353.70
					\$ 670.74
					\$ 2,682.96
1 set	rear bumper sensor	S.Nett			\$ 280.00
1 tube	rear windscreen sealant	S.Nett			\$ 40.00
	rear no plate	S.Nett			\$ 40.00
	To putty & spray paint.				\$ 800.00
	To remove & refix rear windscreen glass.				\$ 100.00
	To transfer tail gate fitting.				\$ 80.00
	To check rear wiring & water leaking				\$ 30.00
	To anti-rust.				\$ 120.00
	Labour charges.				\$ 750.00
TG/VL	TOTAL				\$ 4,922.96