

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							4000.00
RENEW FR BUMPER , FR SUPPORT , BONNET , LHF FENDER & RHF FENDER							
REPAIR LHF / RHF A PILLAR , LHF DOOR & RHF DOOR							
E PNT98000							2800.00
RESPRAY FR BUMPER , BONNET , LHF FENDER , RHF FENDER							
LHF A PILLAR , RHF A PILLAR , LHF DOOR & RHF DOOR							
E PNT88000							100.00
REMOVE & REFIT AC COND & RADIATOR ASSY							
M SUNDRY							80.00
TOP UP AC GAS							
A 54900099							800.00
REMOVE & REFIT DASHBOARD ASSY , GLOVE COMPARTMENT ,							
CENTRE CONSOLE & INSTRUMENT PNL							
A 54900099							800.00
RENEW DRIVER AIRBAG , PASSENGER AIRBAG , AIRBAG CONTROL UNIT &							
AIRBAG FR SENSOR							
A 54900099							400.00
RENEW DRIVER SEATBELT , FR PASSENGER SEATBELT & SEATBELT CATCH							
A 54900099							400.00
RENEW FR INTAKE MANIFOLD							
A 54900099							80.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
E PNT88000							1000.00
CONDUCT CHASSIS ALIGNMENT - CELETTE BENCH							
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
E PNT88000							240.00
RENEW FR WINDSCREEN GLASS							
M SUNDRY							280.00
INSTALL FR WINDSCREEN SOLAR FILM							
M SUNDRY							80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
SUPPLY WINDSCREEN SEALANT							
M SUNDRY							50.00
SUPPLY FR NUMBER PLATE WITH CASING							
M SUNDRY							80.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							80.00
SUPPLY BODY PNL SEALANT							
M SUNDRY							30.00
Sundries							
M COVER-FR BUMPER				1.00	633.00	20.00	506.40
M CAP-FRONT HOOK				1.00	9.00	20.00	7.20
M GRILLE-FRONT BUMPER				1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP,LH				1.00	15.00	20.00	12.00
M COVER-FR BUMPER FOG LAMP,RH				1.00	15.00	20.00	12.00
M GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE				1.00	38.00	20.00	30.40
M LAMP ASSY-FRONT FOG,LH				1.00	303.00	20.00	242.40
M LAMP ASSY-FRONT FOG,RH				1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER,LH				1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,RH				1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,RH				1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER,LH				1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER,LH				1.00	14.00	20.00	11.20
M AIR DUCT-FR BUMPER,RH				1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR				1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
M BEAM COMPLETE-FR BUMPER				1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	540.00
M PANEL ASSY-HOOD				1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH				1.00	43.00	20.00	34.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11833/KEE POH KWANG (JI BAOGUANG) Reg No/Reg Date SMR4949M / 10/01/202 Date In/Mileage / 0 Chassis No KNAF3416MK5051764 Engine No G4FGKH748032 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HINGE ASSY-HOOD,RH		1.00	43.00	20.00	34.40
M PAD-HOOD INSULATING		1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING PAD MTG		13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD		1.00	103.00	20.00	82.40
M LAMP ASSY-HEAD,LH		1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,RH		1.00	1219.00	20.00	975.20
M PANEL-FENDER,LH		1.00	430.00	20.00	344.00
M PANEL-FENDER,RH		1.00	430.00	20.00	344.00
M GUARD ASSY-FRONT WHEEL,LH		1.00	95.00	20.00	76.00
M GUARD ASSY-FRONT WHEEL,RH		1.00	95.00	20.00	76.00
M RESERVOIR & PUMP ASSY-WASHER		1.00	146.00	20.00	116.80
M DUCT-EXTENSION		1.00	5.00	20.00	4.00
M SHIELD-AIR INTAKE		1.00	9.00	20.00	7.20
M DUCT ASSY-AIR		1.00	55.00	20.00	44.00
M CLEANER ASSY-AIR		1.00	174.00	20.00	139.20
M PANEL ASSY-UNDER COVER		1.00	117.00	20.00	93.60
M CONDENSER ASSY-COOLER		1.00	687.00	20.00	549.60
M GUARD-AIR,LH		1.00	28.00	20.00	22.40
M GUARD-AIR,RH		1.00	28.00	20.00	22.40
M RADIATOR ASSY		1.00	646.00	20.00	516.80
M BLOWER ASSY		1.00	656.00	20.00	524.80
M FILLER NECK ASSY-RADIATOR		1.00	28.00	20.00	22.40
M MANIFOLD ASSY-INTAKE		1.00	906.00	20.00	724.80
M MOULDING-WINDSHIELD GLASS		1.00	56.00	20.00	44.80
M COVER ASSY-COWL TOP		1.00	247.00	20.00	197.60
M COVER-AFTER SERIVCE,LH		1.00	11.00	20.00	8.80
M COVER-AFTER SERIVCE,RH		1.00	11.00	20.00	8.80
M S/BELT ASSY-FR LH		1.00	315.00	20.00	252.00
M S/BELT ASSY-FR RH		1.00	317.00	20.00	253.60
M BUCKLE ASSY-FR S/BELT,LH		1.00	179.00	20.00	143.20
M BUCKLE ASSY-FR S/BELT,RH		1.00	114.00	20.00	91.20
M CRASH PAD ASSY-MAIN		1.00	1279.00	20.00	1023.20
M AIR BAG ASSY-PASSENGER		1.00	1275.00	20.00	1020.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	MODULE ASSY-STRG WHEEL AIR BAG			1.00	922.00	20.00	737.60
M	CONTACT ASSY-CLOCK SPRING			1.00	253.00	20.00	202.40
M	SENSOR ASSY-A TYPE CRASH			2.00	54.00	20.00	86.40
M	MODULE ASSY-AIR BAG CONTROL			1.00	1025.00	20.00	820.00
M	BRACKET, IU ADHESIVE			1.00	26.00	00.00	26.00
M	COOLANT (4L)			1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

7% GST on	Nett	26,532.42
	26532.42	1857.27
Total Payable		28,389.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.