

Claim Audit

AUDIT TRAIL			
No.	On	Audit	Remarks
1	29 Dec 2021 13:33	Clm Veh Model Changed	
2	29 Dec 2021 13:33	Clm Created	Reg No: SKM8171M. Policy No: 1800065363-03. Acct Date: 2021/12/28. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R21CT0001
3	03 Jan 2022 10:40	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.
4	03 Jan 2022 10:40	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)
5	03 Jan 2022 10:40	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):
6	03 Jan 2022 10:40	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/12
7	03 Jan 2022 10:40	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.
8	03 Jan 2022 10:40	Clm Registration Modified	Rep:1137->200611.
9	03 Jan 2022 10:40	Clm Veh Model Changed	(207156) AUDI A3 999cc SEDAN TFSI S TRONIC (LED) (A).
10	03 Jan 2022 10:41	Adj Adjuster Assigned	[None] -> ADRIAN LING
11	03 Jan 2022 13:24	Adj Rpt Initiated	
12	03 Jan 2022 13:24	Clm Dtl Modified	Claim Conclusion: -> 3.
13	03 Jan 2022 13:24	Clm Dtl Modified	JPJ Reg. Date: -> 2018/06/18.
14	03 Jan 2022 13:24	Clm Details Notified	
15	03 Jan 2022 15:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/12
16	03 Jan 2022 15:38	Adj Mandate Request	Cur Req:3149.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NO T AUTHORISE REPAIR.
17	03 Jan 2022 15:44	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 300.00. Excess Waived: -> 300.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.
18	03 Jan 2022 18:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/01/12. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after re
19	03 Jan 2022 18:06	Adj Mandate Set	Approved:2708.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.
20	20 Jan 2022 11:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/01/12
21	20 Jan 2022 11:55	Adj Mandate Request	Cur Req:4156.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.

[] Merimen Administrator

[I] Merimen Administrator

[] CELINE FONG

[] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] HUEY YON

[A] HUEY YON

[A] HUEY YON

[A] HUEY YON

[A] SHIAU CHAN

[A] SHIAU CHAN

[I] Azlan, Syazairinda

[I] Lim, Kok-Chong

[I] Lim, Kok-Chong

[A] SHIAU CHAN

[A] SHIAU CHAN

AUDIT TRAIL

No.	On	Audit	Remarks	By
22	20 Jan 2022 14:47	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/01/12. Mandate Remarks: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into M	[I] Lim, Kok-Chong
23	20 Jan 2022 14:47	Adj Mandate Set	Approved:3906.00: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date
From



Date
To



Audit
Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2754153	03 Jan 2022 13:24:11	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKM8171M		11.00