

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg




Supplementary Estimate

Xiao Chan.

CST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1074/2021/JT 18-Jan-22 CHANG 1 of 1 SKM 8171 M AUDI A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	BONNET CATCH HOOK - LOWER <i>Best</i>	\$ 71.00	<i>✓</i> <i>88</i> 56.32
GRAND TOTAL		\$ 71.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
Resigned.

17/01/22. 88

Car-in

19/1/22

wip: 60899

C2/



AIG - ?

3 days

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 8171 M

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Repair	1	\$ 1,987.00	+
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	+
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 536.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 594.00	+
7	FRONT BUMPER TRIM COVER - LH / RH	2	\$ 326.00	+
8	FRONT BUMPER ADAPTER - LH / RH	2	\$ 76.00	+
9	RADIATOR GRILLE Cracked	1	\$ 1,406.00	✓
10	RADIATOR CLOSING ELEMENT Cracked	1	\$ 191.00	✓
11	FRONT BUMPER FOAM FILLER PIECE New	1	\$ 189.00	+
12	FRONT BUMPER SIDE REINFORCEMENT Dented	1	\$ 795.00	✓
13	FRONT BUMPER TOP COVER Lt.	1	\$ 122.00	✓
14	FRONT BUMPER AIR GUIDE GRILLE - LH / RH New	2	\$ 376.00	+
15	AIR COND SITCKER	1	\$ 8.00	+
16	"CAUTION" STICKER New	1	\$ 14.00	+
17	HEADLIGHT	2	\$ 10,910.00	+
18	LIFT CYLINDER - LH / RH	2	\$ 284.00	+
19	LIFT CYLINDER HOSE	1	\$ 68.00	+
20	RADIATOR AIR GUIDE - LH / RH	2	\$ 50.00	+
SUB TOTAL SPARE PARTS			\$ 18,357.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 8171 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	RADIATOR SEAL OUTER - RH	1	\$ 8.00	X	
22	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 12.00	X	
23	Temperature sensor	1	\$ 19.00	X	
23	RADIATOR BRACKET	1	\$ 19.00	X	
24	FRONT NO PLATE	S/N	\$ 60.00	X	
25	SUNDRIES		\$ 250.00	X	
TOTAL SPARE PARTS		:	\$ 18,706.00		
TOTAL LABOUR CHARGES		:	\$ 4,652.00		
GRAND TOTAL		:	\$ 23,358.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Reshaped
Admin L
H.S.
17/01/22