

inchcape

Champion Motors



Co. Reg No. : 19500068E
 GST Reg No. : MR-8500000-9
 No. 2 Pandan Crescent
 Singapore 128462 Tel 66311855

Steve (Lkk)
 12/1/22, 10.00am

with Prejudice
 P/P
 Resurvey Before Spray
 3 dgs

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S8000025 / TPCL	Service Retail Cash Sales Body & Paint Service Retail Cash Sales Body & Paint
	Document No. 0	
	Document Date 31/12/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	SWIFT	2LM1CXF35	25/03/2020	SNC7425E	0	12127	
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JSAAZC13S00303724	K10C1263759	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	S-BMS TP INS: TP VEH: MID46346 DATE OF ACC: 29.12.2021		100.00		50 / 100.00
2	S	S-BMS REPLACE AND REFOCUS HEADLAMP		99.62		99.62
3	S	S-BMS TO RESET ECU AND REPROGRAMME		146.50		146.50
4	S	S-BMS R/I FRONT BUMPER SPOILER TO FAC REPAIR.		146.50		146.50
5	S	S-BMS TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR		146.50		146.50
6	S	S-BMS REPLACE ACC DAMAGED PARTS 586 x1 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS		1172.00		586 1172.00
7	S	S-BMS RESPRAY ACC AFFECTED AREAS 484 x1		968.00		484 968.00
8	1	S35320-52RF0-000 UNIT, HEADLAMP, L / CVT	1.00	1727.40		1727.40
9	2	S71711-53R00-799 BUMPER, FR Y R	1.00	659.55		659.55
10	3	S71732-53R00-000 HOLDER, FR BUMPER SIDE, L	1.00	7.35		7.35
11	4	S71734-52R00-000 HOLDER, FR BUMPER FR, L	1.00	8.40		8.40

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Charge Summary	Total	5,181.82
the Repairer of the following: hence notify • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Parts 2,402.70 Labour 0.00 Sublet 2,779.12 Lubrication/Fluid 0.00 Others 0.00	Total 5,181.82 GST 7.00% 362.73 Less 0.00 Amount Due 5,544.55	

Acknowledged by Repairer

Customer Copy