

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100% ▾

🖨

🔍 Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref: CS/UIO22000023/Vvf3	
146 ROBINSON ROAD			Date: 03/01/2022	
#02-01 UOI BUILDINGSINGAPORE 068909			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 9836E		Veh. Inspected	GBH 3999H
Policy No.			Coverage (\$)	0.00
Claim No.	M11D14302201		Excess (\$)	0.00
Assign From	JOSEPHINE WONG		Assign Date	03/01/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/01/2022		Inspection Date	04/01/2022
Survey held at	AUTO BULLOX PTE LTD			
	53 UBI AVENUE 1 #01-19 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				