

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ✓	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	----------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref: CS/SMO22000033/Ktf3		
50 RAFFLES PLACE #03-03		Date: 03/01/2022		
SINGAPORE LAND TOWERS SINGAPORE 048623		Code: SMO		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SMM 9604B	
Policy No.	Coverage (\$)		0.00	
Claim No.	CMTD2200001/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	03/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/12/2021	Inspection Date	04/01/2022	
Survey held at	NO 8 MANDAI ESTATE			
Repairer	KAH MOTOR.CO.SDN.BHD			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				