

COMFORTDELGRO ENGINEERING

REPAIR ESTIMATE*

VEHICLE NO SHD6642S
 MAKE 23/06/2016
 MODEL I-40

DATE 28.12.21
 CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		de	\$1,052.20
10	BUMPER CLIP		un	\$2.20
1	FRONT BUMPER GRILLE LH		un	\$187.20
1	FRONT FENDER LH		de	\$663.00
1	FRONT FENDER SHIELD LH		un	\$174.90
1	REAR BUMPER BRACKET /LH		un	\$24.60
	SUB TOTAL		1737.20	\$2,104.10
	20.00%			\$420.82
	DISCOUNTED TOTAL		1389.76	\$1,683.28
	Labour Charge			
	Panel Beating		280	\$450.00
	Spray Painting		500	\$500.00
	Check lighting		780	\$60.00
	TOTAL LABOUR			\$1,010.00
	ESTIMATE TOTAL		2169.76	\$2,693.28
			450 1700	
			2 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphir 97495749
 'WP' 28/12/21 @ 5pm
 1/2 Resurvey after repair
 Tanphir e (1/2) 1/2 sum.
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: