From: Dale: 4/1/2028_	Veh No: SCY 8789M Yr Regn: 31/1/2013
Eslimated Cost:	Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
ODIA WS ITP RES I OD RES I EVA I INV I MV	: Truck / Trailer or
To Inspect Vehicle No: SCY 8789 M	Make: Guercedon Benz EDOD C.C 1991
al Workshop m/s Bifost Auto	Make: Merceda Benz EDOD C.C 1991 Colour Beige NC: Insured / Std / NI / NA
of 8 Kaki Br Ave 4 Premier # 01-49	Sp.Reading 132179 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: 27/86030564588
-Policy No.	C/No: WDD2(20482A694743
Claims No.	Gen. Cond: Good / Pair/ Poor / Burnt
Sum Insured: Excess:	Steering: Norder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Leoner / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil Skim / STD A/Rim or
	Tyre Size: F: 245/40/8
(Policy Condition)	R: 265/35/18
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MC OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: 45,000/x	Front Rear R/Bal 6 mm
IDAC Accident Rport: Consistent? : Yes or No	I /Pal /
GIA / PR Seen: Consistent? : Yes or No	P (1811)
Est. Repairs: 15 days Res.: Yes or No Lum Sum: % 3 Val.: Yos or No	D.O.A. 26/12/2021 D.O.I. 4/1/2022 Survey held et Bitrost Xuto
Colli Colli	Des. of Damages : FR) Roan I O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRSWP Vehicle: IN/OUT	best of buildings (A) (April 1)
Dale: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Range: 25,000/2 - 26,000/	2
O. A. I.I. COR: NV \$ 10.5	221.40
Recommended COR: NV \$ 103 COR of LS\$25,400.00 be	zing higher than NV Talim My
MV 45,000/2	
PV 34, 779/2	KTUM Min
NV 10, 221/2	5/2/2022
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, Filo Roturn to?	Transportation:
Add Fee	THE CASE OF THE CA
	: Interview (\$) Photos
Representat:	: Tech. Invs (\$) Offices
Lump Sum/1.8.1: (:	: Weel and (\$
	TOTAL

1. 1

REVO PRIME PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 202021344Z

Estimate

Vehicle No: Model and make: Chassis number

SCY8789M Mercedes Benz E200 WDD2120482A694743

			List price 2013
Qty	Spare parts	_	
		\$	✓ 2,452.44 DDV
1	Bonnet	\$	64.80 93.20 NECV
1	Bonnet emblem	\$	177.05 (6) 6)
1	Bonnet RH hinge	\$	177.05
1	Bonnet LH hinge	S	32.96)NNX
1	Bonnet RH lock spring	\$	32.96 32.96 BRV
1	Bonnet LH lock spring	S	93.50
1	Bonnet RH lock	\$	93.50 ND
1	Bonnet LH lock	\$	203.12 NN
1	Bonnet insulator	\$	1183.80 1,367.30 BRV
1	Front chrome grille		1417.40 1,660.95 BR
1	Front bumper	\$	141+.40 43.55-7 NISX
1	Front bumper top seal	\$	61.00 78.05 MISV
1	Front bumper towing cover	\$	59.47 88
1	Front bumper number plate garnish	\$	50.00 \\ 189.08 BE
1	Front bumper lower grille	\$	-537.91 NSX
1	Front bumper RH LED lamp	\$	178.30 BR
1	Front bumper RH LED lamp garnish	\$	109.30 159.30 BRV
1	Front bumper RH LED lamp chrome cover		537.91 NSX
1	Front bumper LH LED lamp	\$	✓ 78.30 BR ✓
1	Front bumper LH LED lamp garnish	\$	150.20 80
1	Front bumper LH LED lamp chrome cover	\$	
1	Front bumper RH side distance sensor	\$	95.00 217.22 MIS
1	Front bumper RH centre distance sensor	\$	95.00 217.22 SCV
1	Front bumper LH centre distance sensor	\$	95.00 217.22
1	Front bumper LH side distance sensor	\$	16.00 × 38.52 × ECV
4	Front bumper distance sensor rubber seals	\$	16.00 38.52 (EZV 351.20 7 ND)
1	Front bumper distance sensor wire harness	\$	
1	Front bumper RH side retainer	\$	√63.94 } NEG
1	Front bumper LH side retainer	\$	V63.94.
1	Front bumper cemtre bracket	\$	65.00 89.33
1	Front bumper reinforcement	\$	600.00 628.00
1	Front bumper RH inner sponge	\$	69.90 BB
1	Front bumper LH inner sponge	\$	/69.90
1	Front bumper inner sponge	\$	118.57 BRV
1	Front radar sensor	\$	1,197.80
1	Front radar sensor bracket	\$	34.68
1	RH headlamp (2016)	\$	2380. ov 5,123.56 27BR
1	RH headlamp bracket	\$	53.05) NSX

5.123.56 1 7BRV LH headlamp (2016) 53.05~ NS \$ 1 LH headlamp bracket 1,051.46 DD \$ 996-10 1 Front RH fender (2016) 199.05 NDX \$ Front RH fender splash shield (front) 55.70 NS \$ Front RH fender emblem 1,051.46 \$ 1 Front LH fender 199.05 \$ Front LH fender splash shield (front) 55.70 NS \$ Front LH fender emblem 1,235.80 1,370.22 DDV \$ Aircon condenser (2016) \$ 1,468.70 NDX Radiator assy 1,165.00 1,318.79 \$ 7DDV Turbo intercooler \$ 90.30 BRV Front top panel garnish 80.71 \$ Front brace panel \$ 989.30 JBTX 422.10 Support panel 2,544.40 Ach valed \$ 2256.30 Passenger head rest 1.634.50 ? ND \$ Passenger seat belt 344.06 NNY \$ Passenger seat belt buckle 2256.30 2,544.40 Activatede Driver head rest \$ 1,634.00 ? NDX Driver seat belt 344.06 NNX \$ Driver seat belt buckle \$ 231.11 Front RH airbag sensor -231.11 \$ Front LH airbag sensor 2028.30 2,815.10 BTV \$ Bootlid (201b) \$ √ 78.00 Bootlid "E200" emblem \$ J 55.00 HNECL Bootlid centre emblem \$ / 85.42 Bootlid "7G- Tronic" emblem \$ 550.60 Bootlid RH lamp \$ 550.60 Bootlid LH lamp 321.10 M \$ 274.00 Bootlid lock 56.44 ND \$ Bootlid lock catch \$ 355.70 ND> Bootlid chrome moulding \$ 202.18 Bootlid weatherstrip √1,694.20 BR \$ Rear bumper /382.60 BR \$ Rear bumper lower garnish \$ 217.22 \NDX Rear bumper RH side reverse sensor 217.22 \$ Rear bumper RH centre reverse sensor 95,00 217.22 \$ 95,00 Rear bumper LH centre reverse sensor 217.22 NOX \$ Rear bumper LH side reverse sensor 38.52 NEC \$ Rear bumper reverse sensor rubber seal 16.00 4 V 58.00 MISV \$ Rear bumper towing cover 1 \$ 148.44 Rear bumper RH side chrome moulding \$ 148.44 Rear bumper LH side chrome moulding NSX \$ 189.05 Rear bumper centre chrome moulding DDV \$ 235.13 Rear bumper RH exhaust chrome finisher 119.30 DBTV \$ **√** 54.00 Rear bumper RH exhaust chrome finisher bracket 119.30 235.13 \$ DD Rear bumper LH exhaust chrome finisher \$ √ 54.00 Rear bumper LH exhaust chrome finisher bracket \$ 817.00 834.60 BTV Rear bumper reinforcement

Rear bumper RH side retainer

V 45.20 N €CV

\$

				√ 45.2 215.00 223.0 36.0	DONECT
1	Rear b	umper LH side retainer	\$	7 43.2	10 BT/
1		umper centre inner support bracket	\$	215.00 225.	10
2		umper lower brackets	\$		
1		umper RH bracket	\$	45.7	
1		umper LH bracket	\$	45.7	HO DOOL
1	RH ta		\$	454.40 808.5)]
1		llamp lower bracket	\$		1 1
1	LH tai		\$	454.00 808.5	5 BRV
1		llamp lower bracket	\$	38.8	10 7 7 X5X
1	End p	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	\$	980.00 1,275.4	HO DDV
1		anel inner garnish	\$	√167.3	0 BRU
1		ick sensor	\$	385.0	O PNSX
1		ick sensor control unit	\$	475.6	O JUNDA
1			\$	586.50 1,010.9	O BRV
1		^^ (CONTINUED CONTINUED CO	\$	358.0	0 (2000)
1		H fender inner trim	\$	-358.0	O KLDX
1		H fender inner trim	\$	/ 1,455.8	O BTV
1		st silencer	\$	53.00 78.0	10/
-1	Exhau	st silencer gasket	Ψ	23.00	Necel
			\$	57,402.5	9
		-10%		5,740.2	
		-10/0	\$	51,662.3	
		그는 그는 그는 이 이번 때문에 가장하는 것이 아니라 나를 받는다.	Ψ	31,302.3	-

Qty	Spare parts	_	Special Nett pr	rice
1 set	Bonnet insulator clips	\$		70.00 ?NN
1 set	Front bumper clips	\$	30.00	70.00
1	Front number plate	\$	30.00	70.00 NEW
1	Front number plate holder	\$	30.00	50.00
1set	Front RH fender splash shield clips	\$		60.00 Z NAX
1 set	Front LH fender splash shield clips	\$		60.00
1	Radiator coolant	\$		75.00 NN
1 set	Bootlid inner trim clips	\$		70.00 NN
1	Bootlid "C&C" emblem	\$		80.00 NECV
1set	Rear bumper clips	\$	30-00	80.00 NECV
1set	Rear bumper rivets	\$	20.00	60.00 L NECV
1	End panel joint sealant	\$	30.00	70.00 NECV
1	End panel inner garnish clips	\$	30-00	50.00 NEG/
1	Rear compartment panel joint sealant	\$	30-00	80.00 NECV

Labour and painting

(FRONT PORTION)

Labour charges to remove, check, replace and reinstall damages bodyparts.

\$ 600-00 -1,400.00

7 99 W

To panel beating, cut / weld and re-align all affected panels		
Spray painting on affected panels	\$ 800	1,200.00
Check wiring and lighting system	\$	100.00 X XXX
Apply rust coating chemical on affected panels	\$	80.00 NNX 80.00 NNX
Remove and replace aircon condenser, pipes and hoses to assist repair. To refill aircon gas	\$ 120	. 00 240.00
Remove and replace radiator assy, hoses and fan assy to assist repair. To refill radiator coolant	\$	240.00 N N
Re-coding headlamps assy to assist repair	\$ (20	450.00. NAW
Remove and replace front seat belts, buckles and sensors to assist repair	\$	400:00 NNY
Remove and reinstall front seat belts and buckles garnish and trims to assist repair	\$	220.00
Reset and diagnose fault code and control unit after repair	\$ 120	o. or 350.00/
Remove and replace front headrest assy to assist repair		0 = 00 450.00
(REAR PROTION) Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 1000	1,600.00
Spray painting on affected panels	\$ 800	7,400.00
Check wiring and lighting system	Ψ	
Apply rust coating chemical on affected panels	riedged by Repair re: 2	ulangis 120.00 \ NAL
Remove and replace rear inner trims, garnish and boards to assist repair	\$	280.00
	Repairer of the	120.00
Remove and reinstall rear seats, seat belts and carpet to assist repair part(s) during resurvey pert(s) during resurvey pert(s) during resurvey pert to confirmation	2+ damaged	150.00 ASO.00 NN
Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair bewolks at (2) north W s no	suvgy is suvgy is illeged modification	on •
(a) must be resurveyed and replace exhaust silencer and gasket to assist repair repair company from Insurance Company repair to a silencer and gasket to assist repair repair (a) proved from Insurance Company repair (a) and a silencer and gasket to assist repair (a) and a silencer and gasket to assist repair (a) and a silencer and gasket to assist repair (a) and a silencer and gasket to assist repair (a) and a silencer and gasket to assist repair (a) and a silencer and gasket to assist repair (b) and a silencer and gasket to assist repair (b) and a silencer and gasket to assist repair (c) and a silencer and gasket to assist repair (c) and a silencer and gasket to	polementary tem	180.00
Total	nowledged by Repailure: 	

F 21 7 8

Survey 4/1/2422 Tolim lin., 1300hrs Resurvey 5/1/2022 1630hrs Traym Mi

Lump sum repair Repair days 15 Parts 27,723.29 SN 310.00 Labour 3,750.00 31,783.29 @ 2070 6356.66 25,426.63

LS 25,400/2

Telin Win 5/2/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- and display damaged part(s) during resurvey
- . Part prices are subject to confirmation
- . Truju party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of Accident	26/12/1311 Accident Time: 1240 (24-HR-FORMAT)
Accident Place	ATE (CHS) after Alexander
Vehicle Reg. No (Car plate No.)	SCY 8789 M Vehicle Make/Model: E 201
Insurance Company	A16 Policy No. 21004336 28-0
Name of Registered Owner	: Company / Individual Sng Gim Hong
ID of Registered Owner	: Co Reg No: Owner's NRIC No: \$15886261
	: Co Contact No: Owner's Contact No: 9387 3557
DRIVER'S Name	OW YUN cong DRIVER'S NRIC No: S96200431
DRIVER'S Date of Birth	28/5/1996 DRIVER'S License Pass Date 23/1/2016
Relationship bet. Owner & Driver	: Spouse \ Parents \Clyidden\ Sibling \ Employee\ Others:
DRIVER'S Address	: 336 climati Are 1 #25-34 S(120536)
DRIVER'S Contact No./ Alt No.	:1) 9670 9773 2)
DRIVER'S Occupation	: INDOOR \OUTDOOR (eg. working inside or outside of an ofc)
Email Address	2020MBC @ gmail.com
Weather & Road Surface	: CLEAR DRY \ RAINING & WET \AFTER RAIN & WET
Reporting Type	: Reporting Only \ Claim Other Party \ Claim Own Insurance
Was the accident reported to the poli Was there any video Captured by car	
Other	Party Driver's Particulars (if any)
Vehicle Reg No: SKM 2367E	Vehicle Reg No: SLQ 7420 7
Vehicle Make\Model:	Vehicle Make\Model:
Name DRIVER:	Name DRIVER:
C No. DRIVER:	IC No. DRIVER:
DRIVER'S Contact & add	DRIVER'S Coutest & add

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

914-12022

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 - 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

m	m			
Policyholder's Signature / Date & Time	Driver's Signature (If driv & Time	Witnessed by Reporting Centre Personnel		
Sketch Plan				
			A: SCY 8789M	
			13: SKM 2367E	
		E TO THE STATE OF	(· SLQ74207	
			D: SICW 70204	
		A		
		(3)		

	1 WA	s tro	avellin	1	alonh	AY	F. (C/1)	· The	VIL	1616	in dr	1
	01-		1 -	LAA	and the second	2150	Cas In	16 1	MI	a	hage	
	inne w	Am	/ 3	In h	2162	74	in 964	VES	51	614	that	4
	(mpxq	120	11	- 1:	Lear!	more	French	L	610	0 10	14	
	caused			clr	ti	more	MINTALE	1	N4	- 179	12	
	vehicle	in 1	MA.				14. 人、人、大工程			13/4/2		
210.9	100	THE RESERVE	Pr. L Danger		San Transfer	BANK BANK BY						
		3 5			. , 1138		17 1 17 17 17 17 17 17 17 17 17 17 17 17					
3.78					Wash at N		ber der to all		03 200 03			
			e de la companya del companya de la companya del companya de la co					n 'v salt	100	THE REAL PROPERTY.	No. of the last of	
			1000000									
	100											
	1											
												Miles
		Marian III										
		SELECTION	3 1 2 3 1 1 1 1		12/15/15							
		The second										
115 59	7.											
	The state of the s	OA SOCIETISMA	2 (100)	11 11 11 11	A SHOW IT	Hart Street	A STANSON OF	COLO INCOLO I				
			1									
	0.00	4 1 1 1 1 1 1 1 1 1		1000			an ager est.	A THE PARTY				
				17.47								7496
1.1.1.1.1.1					greet many to							
ni i												
4.1.191	The same of the sa										HE MAKE A	1400
1												
							and the second second					
4.8	The state of the state of		Later to	0 10	77 78	27750354	15-304-50	73 / 73/4	0 (11)	20078	Tibin.	3 77 1
					3130							
	f G. arr											
				160	25 J	pata medi.		0.8.00	711		for the second	NAY.
				5 35 T 4	. 25.	Acres 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			40.006.153			1/1
T VIII			Petro III e de								Man A A A	-
	W-16											
Decl	aration											
We d	declare the fo	regoing par	ticulars are	true in	every res	pect.						
		1 1										
	1				,							
	har				h)						

Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	6261	
Vehicle No.:	SCY8789M	
Vehicle to be Exported:	No	
Intended Deregistration Date:	05 Feb 2022	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	E 200 BLUEEFFICIENCY	
Primary Colour:	Beige	
Manufacturing Year:	2012	
Engine No.:	27186030564588	
Chassis No.:	WDD2120482A694743	
Maximum Power Output:	135.0 kW (181 bhp)	
Open Market Value:	\$50,766.00	
Original Registration Date:	31 Jan 2013	
First Registration Date:	31 Jan 2013	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$50,766.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	30 Jan 2023	
PARF Rebate Amount: Intended COE Rebate Details	\$25,383.00	
COE Expiry Date:	30 Jan 2023	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$95,501.00	
COE Rebate Amount:	\$9,396.00	
Total Rebate Amount:	\$34,779.00	

The information contained herein is correct as at 05 Feb 2022

OK

MV 45,000/2 PV 34,779/2 NV 10,221/2

Totin luin 5/4/2022

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



ON YOUR CAR SAVE UP TO INSURANCE RENEWAL!

Jan 2022 Honda Fit 1.3A \$89,500

GET A CHEAPER QUOTE NOW

SGEARMART.COM

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Ways of Selling Advertiser Login



2022 Honda Fit 1.3 CVT. Brand New, Beautiful Air Light Blue, Deposit \$5K Think One Automobile StarAd



Browse by Category

Post an Ad

7 vehicles

Mercedes-Benz E200

Depreciation

Reg Date 2013 Eng Cap

Mileage

Sort by Date Posted

Advanced Search C

Any

Veh Type

Available

Search Selection

Mercedes-Benz E200

Απν

\$22,760 /vr

Απν

23-May-2013

1.991 cc

Anv

91,000 km

Anv

Available

Mercedes-Benz E-Class E200

\$54,800

Beautiful Black On Black With Warm Walnut Interior Trim! Very Well-Loved And Taken Care Of. View To Believe! A Picture Speaks A

Luxury

✓ 20 results/page

Posted: 12-Jan-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200

Mercedes-Benz E-Class E200

\$51.800

\$19,140 /vr

24-Jun-2013

1.991 cc

95,000 km

Luxury

Available PREMIUM AD

PREMIUM AD

DIRECT OWNER

Bank/In House Loan Available, One Of The Lowest Depreciation In The Market, Call Our Sales Consultant For Viewing Now! Allmotoring,sg

Thousand Words! Contact Any Of Our Friendly Sales Representatives For Viewing Now! Welcome High Trade-in High Loan!

Posted: 20-Jan-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200

Mercedes-Benz E-Class E200

\$21,630 /vr

01-Jul-2013

1,991 cc

87,000 km

Available Luxury

Only 2 Owners. Low Mileage Agent Car Maintained By Cycle & Carriage. All Major Wear And Tear Parts Replaced. Sporty Metallic Grey Exterior Perfectly Paired With Premium Brown Leather Interior. Well Maintained Unit. High Loan Available With Low Interest Rates. Cally.

Posted: 28-Jan-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200

\$53,800



Mercedes-Benz E-Class E200

\$59,000

\$21,000 /vr

11-Sep-2013

1,991 cc

Luxury Available

Accident Free, Low Mileage Of 38000km, 5 New Pirelli P Zero Tyres, Excellent Bodywork, Will Retain Numberplate, Regularly Serviced, Tip Top Condition Interior/Exterior.

Posted: 03-Feb-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200



Excellent Grip Peformance Michelin 18" Tyre

ON SALE Michelin PS4 (225/40/18). Visit us @ 32 Old Toh Tuck Rd, #01-09, I-biz Centre S(597657). Call 66862255 now! Find out more!



Mercedes-Benz E-Class E200

\$58,999

521,390 /yr

02-Oct-2013

1,991 cc

89,120 km

Luxury

Available

100% Loan Approval, Fully Serviced By Agent, Original Facelift R17 Model, Take Back Minimum \$36K On 10/2023 COE Expired, 12k Depreciation Per Yr Only,, Low Mileage, Well Maintained Condition, New Paintwork, No Repairs Needed And Comes With 6 Months Warra...

Posted: 16-Jan-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200



Mercedes-Benz E-Class E200

\$55,800

\$19,300 /yr

04-Oct-2013

1,991 cc

123,000 km

Luxury

Available

Buy Back \$32k At End Of COE. Promo 1.88% Bank Loan Interest Rate. Balloon Scheme Available. Cycle And Carriage Unit. Agent Service And Well Maintain. Flexible In-House Loan Available. Please Call Or Visit Us For More Details.

Pure Motors Pte Ltd

Posted: 04-Feb-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200



Mercedes-Benz E-Class E200

\$60,800

\$20,080 /yr

13-Dec-2013

1.991 cc

79,000 km

Available Luxury

Buy Back \$32k At End Of COE. 1 Owner Only. Promo 1.88% Bank Loan Interest Rate. Cycle & Carriage Unit. Good For Future COE Renewal, Black With Black Interior, Agent Service And Well Maintain, Balloon Scheme Available, Please Call Or Visit Us For More Details,

Pure Motors Pte Ltd

Posted: 17-Jan-2022 Tags: 2013 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200

Save this search criteria, to get email alerts whenever a match is found.