

Date: 03/01/2022

Vehicle No: SMR546T

Model: TOYOTA CHR HYBRID

Chassis: ZYX102130684-2018

Reg.Year: 2019

Third Party Insurer: INDIA

Third Party Veh No: YM1961E

Date of Accident: 31/12/2021

Estimator: TING AN

Surveyor:

Not Authorized
Surveyor B. P. P. M.
4-5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1		<i>Car</i> \$1,727.00
2	FRONT BUMPER	1		<i>CM</i> \$399.00
3	FRONT BUMPER SIDE BRACKET RH	1		<i>DIY</i> \$115.00
4	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		<i>MIY</i> \$88.00
5	FRONT BUMPER LOWER GRILLE	1		<i>DIY</i> \$505.00
6	FRONT GRILLE	1		<i>Per</i> \$173.00
7	FRONT FENDER RH	1		<i>R</i> \$826.00
8	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>Per</i> \$65.00
9	FRONT FENDER INNER SHIELD RH	1		<i>CM</i> \$236.00
10	FRONT FENDER WHEEL ARCH GARNISH COVER RH	1		<i>MIY</i> \$143.00
11	FRONT RIM RH	1		<i>Per</i> \$2,128.00
12	FRONT ABSORBER RH	1		\$493.00
13	FRONT LOWER ARM RH	1		\$760.00
14	FRONT KNUCKLE ARM RH	1		\$698.00
15	FRONT WHEEL BEARING RH	1		\$697.00
16	FRONT BONNET	1		REPAIR
SUB TOTAL				\$9,053.00
LESS 25%				-\$2,263.25
PARTS TOTAL				\$6,789.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>Per</i> \$50.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>Per</i> \$30.00
3	FRONT FENDER WHEEL ARCH COVER CLIPS RH	1		<i>Per</i> \$30.00
S/N TOTAL				\$110.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

\$700.00

400

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT BONNET & ETC.

\$700.00

600

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 03/01/2022

Vehicle No: SMR546T

Model: TOYOTA CHR HYBRID

Chassis: ZYX102130684-2018

Reg.Year: 2019

Third Party Insurer: INDIA

Third Party Veh No: YM1961E

Date of Accident: 31/12/2021

Estimator: TING AN

Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM RH & ETC. \$200.00 ?

TO WHEEL ALIGNMENT & BALANCING. \$80.00 20%

TO DAIGNOSIS FAULT CODE & RESET MEMORY. \$120.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$100.00 20%

LABOUR TOTAL \$1,900.00

TING AN TOTAL \$8,799.75

Head office

6 Kung Chong Road Singapore 159143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500
Tel (+65) 6484 9919 | Fax (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel (+65) 6481 1522 | Fax (+65) 6481 1011

